

Tender Specification - Pricing Schedule

Tenderers should enter their price for each item in the Price column.

Category	Location / Defect Details	Required Works	Price (£ ex VAT)
1	A Abbey Path The drop lock has half detached from the column door and needs drilling out and refixing.	Refix door lock	
1	A Acorn Green Secondary isolation upgrade required, tails upgrade required. Vandalised Quantum 4 LED lantern – broken lens covers and the LED's are dimmer.	Replace lantern	
1	B Acorn Green New column required – heavy corrosion inside and the column is very soft and malleable.	Replace column	
1	C Acorn Green (opp 14) Broken BICC Mains Cut-out fuse carrier. Secondary isolation upgrade required, tails upgrade required. The column has water in the base below ground, note only it's solid at present.	Replace lantern + fuse carrier	
1	C Acorn Green (rear of 8) New column required, corroded base with a hole in it. Broken Mains Cut-out.	Replace column	
1	1 Amberstone New pole box required. Pole box has splits in the side where the old photocell was fitted, no door lock. Wired through the top of the box. Pole box has no Earth path to it. Pruning required.	Replace lantern & pole box + Earthing + pruning	
1	2 Amberstone New pole bracket required – heavy corrosion with holes in it. Pole box has no Earth path to it. Wooden pole needs clearing of Ivy. Water ingress in the photocell.	Replace lantern & pole bracket + Earthing + pruning	
1	4 Amberstone No Secondary Isolation. Pole box has no Earth path to it. The box is very loose and needs additional fixing screws to secure it to the pole. Pruning required to access the column to work on it. Lantern fibreglass is heavily broken down.	Replace lantern, refix pole box + Earthing + pruning	
1	5 Amberstone Pole box has no Earth path to it. The pole box is upside down and wired through the top. Wooden pole needs clearing of Ivy.	Replace lantern & reconfigure pole box + Earthing + pruning	
1	D Amberstone View No Secondary Isolation. There is corrosion with a hole in it at the Swan Neck bracket joint with the column. Old faded blank sign needs removing.	Replace lantern & Swan Neck bracket + remove sign	
1	A Battle Road Vandalised lantern – smashed lamp and diffuser which has the remains hanging on the hinges. Pruning required.	Replace lantern + pruning	
1	A Beckenham Close Secondary isolation upgrade required, tails upgrade required. Vandalised Sox lantern with split and leaking diffuser. Broken lamp strap in the lantern. Day burning Sox lantern.	Replace lantern	
1	B Beckenham Close Secondary isolation upgrade required, tails upgrade required. Vandalised Sox lantern with split and leaking diffuser that is cable tied in place. Not working –not financially viable to repair – new lantern required.	Replace lantern	
1	A Bell Banks Road Vandalised lantern, SRL gear tray cable tied in place.	Replace lantern	
1	D Bell Banks Road Vandalised lantern.	Replace lantern	
1	E Bell Banks Road New pole box required – one lock catch has completely corroded away, the other is heavily corroded too. Secondary isolation upgrade required. Vandalised lantern. Lantern fibreglass is heavily broken down.	Replace lantern + pole box	

Category	Location / Defect Details	Required Works	Price (£ ex VAT)
1	A Bell Banks Road footpath to Archery Walk Broken pole box door hinges. No Secondary isolation. Vandalised lantern – no access to this when the ground is wet.	Replace pole box & lantern	
1	B Bell Banks Road footpath to Archery Walk New pole box required, corroded with holes in it. Snapped Earth to the pole box. No access to this when the ground is wet.	Replace pole box & lantern + Earthing	
1	C Bell Banks Road footpath to Archery Walk New pole box required, corroded with holes in it. No access to this when the ground is wet.	Replace pole box & lantern	
1	C Blossom Walk New column required – corroded inside with holes in the column. Secondary Isolation upgrade required, tails upgrade required.	Replace column	
1	A Bramble Drive New column required corroded with hole in the base.	Replace column	
1	C Bramble Drive New column required, malleable and very thin at base, also malleable by the door entry. Secondary Isolation upgrade required, tails upgrade required. Loose Earth bolt, Earth cable wrapped around instead of permanent connection.	Replace column	
1	D Bramble Drive New column required corroded with hole in the base.	Replace column	
1	E Bramble Drive New swan neck required, corroded joint with hole in it.	Replace Swan Neck bracket & lantern	
1	M Bramble Drive New column required corroded with holes in the base.	Replace column	
1	B Caburn Way Photocell has a lot of water ingress.	Replace photocell	
1	F Cackleberry Close New column required, corroded base with hole in it. Secondary Isolation upgrade required, tails upgrade required.	Replace column	
1	A Carriers Path Secondary Isolation upgrade required. Cast column door has a snapped off hinge pin, the door is cabled tied in place. This is not replaceable – note only. Day burning very poor condition Windsor lantern.	Replace lantern with SL10	
1	B Derwent Close Secondary Isolation upgrade required. Tails upgrade required. The Earth block is not fixed back, just floating in the column. The column is leaning two ways and is loose in the ground.	Replace lantern + RTV	
1	G Derwent Close New column required corroded at ground level with a hole in it. Tails upgrade required.	Replace column	
1	C Ditchling Way Missing column door – no spares for this Cast Iron column. The plastic cover currently in use is broken and has a big hole in it. Broken Mains Cut-out.	Replace column	
1	C Eastwell Place New column required. The column is solid above ground but is wet and heavily corroded below ground. The column is also full of water. No Secondary Isolation – no room because the Mains Cut Out and Pilsta supply cable are taking up all the room.	Replace column	
1	C Elm Green (Harmers Hay Road) New column required corroded column with holes and splits in it. UKPN? have cut the cable inside the column, the cable is still in the column it's not been pot ended. The lantern supply cable is not fed by anything.	Replace column	
1	E Elm Green (Harmers Hay Road) Secondary Isolation upgrade required, tails upgrade required. Photocell has water ingress.	Replace lantern	
1	A Elmsdown Place Vandalised / cracked diffuser.	Replace lantern	
1	J Ersham Road New column required – heavy corrosion at ground level with a large hole in the base. Secondary Isolation upgrade required.	Replace column	
1	L Ersham Road Broken photocell side which will let water ingress in. Resident is reporting this new column did not get the old signs transferred over, one of which was a 30 MPH sign.	Replace photocell	

Tender Specification - Pricing Schedule

Category	Location / Defect Details	Required Works	Price (£ ex VAT)
1	N Ersham Road No Secondary Isolation. Pole box is very corroded with holes in it.	Replace pole box and lantern	
1	C Ersham Way New lantern required, the old Son ballast has melted its way through the gear tray and the gear tray is now taped in place. Secondary Isolation upgrade required. Lantern fibreglass is heavily broken down. Badly discoloured diffuser.	Replace lantern	
1	A Falcon Way Secondary Isolation upgrade required. The column door is corroded with some of the top catch-plate area missing (solid column with water in the bottom) New Swan Neck bracket required, corroded joint with a hole in it.	Replace lantern, Swan Neck Bracket & column door	
1	B Featherbed Lane This is a new wooden pole with everything transferred over. One of the pole bracket bolts is now missing and needs replacing as the bracket is now loose. The pole box is only partially fixed by the missing pole bracket bolt, just a few turns in and is very loose. There is no Earth path to the pole box. The old photocell in the top of the pole box is leaking.	Refix pole bracket and box + Earthing + replace photocell	
1	D Fern Green (rear of 6 in service road) New column required – corroded with holes in it and very wet inside too.	Replace column	
1	E Fern Green Secondary isolation upgrade required, tails upgrade required. New Swan Neck bracket required – heavily corroded neck joint with a hole in it.	Replace lantern & Swan Neck Bracket	
1	B Fir Tree Close Vandalised lantern missing it's SRL diffuser.	Replace lantern	
1	D Garfield Road The column is going soft and has lots of internal corrosion. Secondary isolation upgrade required. Old sign straps need removing from the column.	Replace column	
1	A Grovelands Road The pole box is installed upside down with Mains cable also going through the top, very wet backboard as a result. New pole box required. No Earth path to the pole box backing plate.	Replace pole box and lantern	
1	B Grovelands Road Heavily corroded pole box with holes in the base, New pole box required. No Secondary Isolation.	Replace pole box and lantern	
1	C Grovelands Road The pole box is upside down with the Mains cable also going through the top. The pole box has no Earth path to it. Broken Mains Cut-out with the Live connector block exposed as the cover is loose and not fixed down. New pole box required. Ivy clearance required. There is also a second pole box on this column with a Nema cell in the top and the front missing from the MCO as well as the fuse out, so cannot be in use at present.	Replace pole box and lantern + pruning	
1	C Harebeating Crescent New column required – corroded below the door entry hole with holes in the column. Secondary isolation upgrade required, tails upgrade required. Lantern fibreglass is heavily broken down.	Replace column	
1	D Harebeating Crescent Axia 16 LED lantern with 3 LED sections no longer working.	Replace lantern	
1	G Harebeating Drive New 5m square corner door required, the crumple zone has been caved in by numerous vehicle impacts and another one may take out the Mains cut-out.	Replace door	
1	H Harebeating Drive New column required, the base of the column is corroded with a hole in it. Secondary isolation upgrade required. Column is leaning two ways. Water ingress in the photocell.	Replace column	
1	N Harebeating Drive New column required, holes in the corrosion below the door entrance hole. Axia 16 LED lantern with 2 x dropped out LED's no longer working. Old sign strap needs removing.	Replace column	

Tender Specification - Pricing Schedule

Category	Location / Defect Details	Required Works	Price (£ ex VAT)
1	B Hawks Road Broken pole box door hinge. Loose backboard, Secondary Isolation is hanging loose. Water ingress in the photocell.	Replace pole box and lantern	
1	C Hawks Road Pruning required. Broken / vandalised photocell.	Replace photocell + pruning	
1	E Hawks Road The Mains cable is wired through the top of the pole box. Secondary Isolation tails upgrade required. Secondary Isolation needs fixing, it is currently floating upside down in the pole box.	Replace pole box and lantern	
1	F Hawks Road Water ingress in the photocell.	Replace photocell	
1	G Hawks Road New pole bracket required – heavily corroded with holes in it. The lantern will also need replacing if the top fixing bolts do not undo.	Replace pole box and lantern	
1	I Hawks Road The Mains supply cable comes through the side of the pole box. It's a wet box and the backboard has disintegrated.	Replace pole box and lantern	
1	N Hawks Road Very corroded pole bracket needs replacing. Broken pole box hinges, so the door falls off. No Secondary Isolation. No Earth path to the pole box. Wooden pole needs clearing of Ivy.	Replace pole box and lantern + pruning	
1	C Hawkstow Crescent New column required – corroded base with holes in it and also below the door entry hole. Secondary Isolation upgrade required, tails upgrade required. SRL lantern fibreglass is heavily broken down. The diffuser is heavily discoloured.	Replace column	
1	B Hawkstow Gardens New column required – corroded with a hole in the base. SRL lantern fibreglass is heavily broken down. The diffuser is heavily discoloured.	Replace column	
1	C Hawkstow Gardens New column required – corroded below the door entry hole with holes in it. The column joint with the Swan Neck bracket joint is heavily corroded but with no holes. Day burning – photocell needs replacing.	Replace column	
1	B Hawkswood Drive Water ingress in the photocell. New 5m round corner door required, multiple hits to the existing one and the locator lug has snapped off – door cable tied in place.	Replace photocell + door	
1	A Hawkswood Road Vandalised lantern, fibreglass is heavily broken down. Water ingress in the photocell.	Replace lantern	
1	A Hawthylands Drive New column required, the column is corroded in the base and has a hole in it. Old blank faded sign needs removing. Broken Mains Cut-out fuse carrier.	Replace column	
1	C Hawthylands Drive New column required, the column is corroded in the base and has a hole in it. Old blank sign needs removing.	Replace column	
1	C Hawthylands Road Corroded column base and swan neck joint, no holes yet but column is full of water and it is corroding inside too, probably best to replace it now. The door is corroded on the bottom and the location lug has broken off, door cable tied in place.	Replace column	
1	E Hawthylands Road Failing lantern only 2 of the 4 LED sections work.	Replace lantern	
1	J Hawthylands Road Wooden pole needs clearing of Ivy to be able to work on this light. Pole box is wired through the top and leaks. Pole box has no Earth path to it.	Replace pole box and lantern + pruning	
1	L Hawthylands Road New pole bracket required - corroded with holes in it. No Secondary Isolation. The Mains supply cable is wired through the top of the pole box. Pruning required. Water ingress in the photo cell.	Replace pole box, bracket and lantern + pruning	
1	M Hawthylands Road New column required – corroded below the door entry hole with multiple holes in the column. Old sign strap needs removing. Pruning required.	Replace column + pruning	

Tender Specification - Pricing Schedule

Category	Location / Defect Details	Required Works	Price (£ ex VAT)
1	O Hawthylands Road The box is installed upside down, therefore the cables are wired through the top and allowing the box to leak. No Secondary Isolation, Pole box has no Earth path to it. Wood pole requires Ivy clearance.	Replace pole box and lantern + pruning	
1	S Hawthylands Road Broken pole box. The Mains cables are going through the top of the box and the supply out to the lantern is through the bottom. Pole box has no Earth path to it. Mains Cut-out is taped together.	Replace pole box and lantern	
1	B Hayland Green This is just a stump cut down at six feet instead of at the column neck for some reason, this is because of a huge hole in column base at ground level. A resident has requested it be cut down lower as it looks awful.	Replace column	
1	C Hayland Green o/s 8 Broken Mains Cut-out. Secondary Isolation upgrade required, tails upgrade required. The column is very loose below ground, it's in Tarmac which is solid but the Tarmac is a pivot, it is so wet underground the column moved to a big sloped angle when I started going up a ladder.	Replace lantern & RTV	
1	A Ingrams Way Secondary Isolation upgrade required, tails upgrade required. The door location lug has corroded off and the door is cable tied in place.	Replace lantern + door	
1	C Ingrams Way Heavily corroded column base – no holes yet, approx. a year or so left.	Replace column	
1	H Ingrams Way New column required – heavily corroded base with multiple holes in it. Leaning but solid in the ground.	Replace column	
1	I Ingrams Way Secondary Isolation upgrade required, tails upgrade required. New 5m round corner door required.	Replace lantern + door	
1	J Ingrams Way New column required, corroded base with a hole in it. Heavily corroded Swan Neck bracket joint – no holes yet. Secondary Isolation upgrade required, tails upgrade required.	Replace column	
1	D Laburnum Green (Harmers Hay Road) New column required, corroded inside and has holes in the column.	Replace column	
1	A Lansdowne Road New column required the column is corroded below the door entry hole and has holes in it. The column door is also corroded with holes in it. Old faded sign need removing from the column. Old sign strap needs removing from the column. Broken Mains Cut-out fuse carrier.	Replace column	
1	A London Road (South) New column required – the entire base is soft and malleable, heavily corroded inside but no holes yet. Old empty bus stop timetable board is too low, too loose and needs removing if no longer any use. Water ingress in the photocell.	Replace column	
1	B London Road (South) No Secondary Isolation – no room with the remote gear. Vandalised lantern. Old bent in half sign needs removing. Lantern fibreglass is heavily broken down. Badly discoloured diffuser. Note this is an 8m column on a T-junction.	Replace lantern with SL9 + remove sign	
1	D London Road (south) No Secondary Isolation. Earth upgrade to the pole box is required. The pole box is wired through the top of the box and leaks.	Reconfigure wiring and seal box, install Secondary Isolation + Earthing	
1	F London Road (South) New pole box required – broken door hinges. No Secondary Isolation. Old relay base needs removing. Water ingress in the photocell.	Replace pole box and lantern	
1	G London Road (South) Secondary Isolation upgrade required, tails upgrade required. Water ingress in the photocell. Old Faded blank sign needs removing.	Replace lantern + remove sign	

Tender Specification - Pricing Schedule

Category	Location / Defect Details	Required Works	Price (£ ex VAT)
1	J London Road (South) No Secondary isolation. Lantern is wired through the top of the pole box which leaks. The lantern needs rewiring and the box sealed. No Earth path to the pole box.	Reconfigure wiring and seal box + Earthing	
1	K London Road (South) Pole box is heavily corroded with holes in it. No Secondary Isolation. Earth upgrade to the pole box is required.	Replace pole box and lantern	
1	L London Road (South) New pole box required – no door and the front is partially taped up. An animal has been living in it and has chewed the Mains supply cable. The Mains Cut-out is hanging out of the front of the box. The new lantern cable is coiled up and has never been connected to the Main. No Secondary Isolation. Missing pole bracket fixing bolt.	Replace pole box, install Secondary Isolation and refix bracket	
1	C London Road (North) New column required, badly corroded below the door entry with lots of holes in it. No Secondary isolation. Old faded sign needs removing.	Replace column	
1	H London Road (North) New column required – badly corroded at the base with holes in it. Old sign strap needs removing.	Replace column	
1	B London Road Cuckoo Trail to The Cedars Missing 5m round corner column door.	Replace door	
1	D London Road Cuckoo Trail to The Cedars New lantern required, gear fault and not working.	Replace lantern	
1	F London Road Cuckoo Trail to The Cedars Missing specialised small door for this mid hinge column, plastic cover taped in place. Requires a metal temporary door cover Tespa banded in place.	Supply and fit temporary door and secure	
1	J London Road Cuckoo Trail to The Cedars Vandalised lantern is not working. Secondary isolation cover is missing,	Replace lantern	
1	E Manor Park Road The column is full of water up to the bottom of the door entry hole which is over a foot out of the ground.	Drain water, find cause and seal	
1	F Manor Park Road New Swan Neck bracket required. Heavily corroded joint which has a hole in it.	Replace lantern & Swan Neck Bracket	
1	I Manor park Road Vandalised Sox diffuser.	Replace lantern	
1	B Meadow Road New column required, very corroded with holes in it. The column door is also corroded. Column is leaning but solid in the ground. The column Earth bolt has detached and is hanging free leaving no Earth path to the column.	Replace column	
1	D Meadow Road Secondary Isolation upgrade required, tails upgrade required. Day burning Sox lantern.	Replace lantern	
1	E Meadow Road Secondary Isolation upgrade required, tails upgrade required. The lantern is full of water, leaks through a broken photocell seal, the lantern is full of moss as a result. Old faded blank sign needs removing from the column. The Mains Cut Out looks like a panel is missing and it is oozing tar out of it.	Replace lantern + remove sign	
1	A Mill Road New pole box required – it is corroded with holes in it. No Secondary isolation, Pole box has no Earth path to it.	Replace pole box and lantern	
1	C Mill Road New pole box required – it is falling apart with lots of corrosion and holes in it.	Replace pole box and lantern	
1	E Mill Road Heavily corroded pole box with holes along with two empty photocell holes in the side too. The pole bracket is bent and angles downwards, this will allow the lantern to slowly fill with water and eventually short out when there is enough water inside. Water ingress in the photocell.	Replace pole box, bracket and lantern	

Category	Location / Defect Details	Required Works	Price (£ ex VAT)
1	F Mill Road Corroded pole box with holes in it. Earth path to the pole box requires an upgrade.	Replace pole box and lantern	
1	G Mill Road New pole box required – it is corroded with holes in it.	Replace pole box and lantern	
1	H Mill Road New pole box required – it is corroded with holes in it. Vandalised photocell. There is a 1.5mm Earth cable to the box which is insufficient.	Replace pole box and lantern	
1	P Mill Road New pole box required – it is corroded with holes in it. Earth bolt has broken away from the pole box corroded area, no longer an Earth path to the pole box.	Replace pole box and lantern	
1	9 New Road New pole box required – very corroded with holes in the sides and the bottom missing completely. Pole box Earth upgrade required.	Replace pole box and lantern	
1	D Oak Tree Way New column required – corroded with holes in the base. Secondary Isolation upgrade required, tails upgrade required. Ideally this column needs moving 1m to the right when it is replaced, currently it is situated in front of an open drive and would be much better placed on the boundary line between the gardens/drives.	Replace column	
1	A Old Orchard Place New Swan Neck bracket required – corroded joint with a hole in it.	Replace lantern & Swan Neck Bracket	
1	C Old Orchard Place Secondary Isolation upgrade required. Very thin Swan Neck bracket joint due to heavy corrosion.	Replace lantern & Swan Neck Bracket	
1	E Old Orchard Place New column required, very corroded base with lots of holes in it. Secondary Isolation upgrade required.	Replace column	
1	1 Old Road UKPN have fitted a new Mains Cut-out into one of their Diamond boxes. New pole box required – broken door. Will then require new tails to the adjacent UKPN box and the lantern rewired.	Replace pole box and lantern	
1	2 Old Road No Secondary Isolation. Pole box has no Earth path to it. The Mains Cut-out is missing its lower shield. The pole bracket is bent and needs replacing as rainwater will continually run down into the lantern eventually causing it to fail. Lantern fibreglass is heavily broken down.	Replace pole bracket and lantern	
1	3 Old Road Pole box has no Earth path to it. Broken BICC Mains Cut-out fuse carrier.	Replace fuse carrier + Earthing	
1	5 Old Road Corroded pole box with holes in it. No Secondary Isolation. Pole box has no Earth path to it. Pruning required. Vandalised Sox lantern.	Replace pole box & lantern + pruning	
1	C Sandbanks Way Secondary Isolation upgrade required. Requires an ants nest to be dug out and powdered inside. Very loose Swan Neck bracket that does not tighten up further – new Swan Neck bracket required. Lantern fibreglass is heavily broken down. Heavily discoloured diffuser. Old blank faded sign needs removing. Water ingress in the photocell.	Replace lantern & Swan Neck bracket + Remove ants' nest and treat	
1	A South Road Pole box only – the pole bracket and lantern are missing – requires a swivel pole bracket due to the cable locations on the wooden pole. Pole box has no Earth path to it.	Replace missing pole bracket lantern	
1	B South Road Mains cable and lantern cable are both wired through the top of the pole box. Pole box has no Earth path to it.	Replace pole box	
1	H South Road Secondary isolation upgrade required – dual fused required as there is a supply out from this column too. Photocell is full of water.	Replace secondary Isolation unit & photocell	
1	B Southerden Close New column required – corroded with holes in the base. New lantern required, Vandalised lantern that leaks and has blown gear. Secondary Isolation upgrade required. Missing column door. Column Earth upgrade required.	Replace column	

Category	Location / Defect Details	Required Works	Price (£ ex VAT)
1	C Southerden Close New column required – corroded with major holes in the base. Secondary Isolation upgrade required. Pruning required.	Replace column + pruning	
1	1 Squab Lane Water ingress in the photocell.	Replace photocell	
1	A St Wilfrids Green Gear tray has fallen apart and the gear is hanging loose. Cast column door has a crack half way through it – note only, not replaceable.	Replace lantern	
1	D Station Road Vandalised lantern – not working, ignitor has also failed.	Replace lantern	
1	H Station Road Secondary Isolation upgrade required. Tails upgrade required. Vandalised diffuser.	Replace lantern	
1	I Station Road New scrolled Swan Neck bracket required – joint is corroded with holes in it. The lantern fibreglass is heavily broken down.	Replace lantern & Swan neck bracket	
1	J Station Road No Secondary Isolation. Wired through the top of the pole box, lantern rewire required and top of the box sealed. Pruning required.	Replace lantern & seal box + pruning	
1	K Station Road No Secondary Isolation. Pole box has no Earth path to it. No Neutral block just a connector block in use. The existing door lock has been cut at some point to allow access to the box and the door no longer shuts tightly. New pole box required. Lantern fibreglass is heavily broken down.	Replace pole box and lantern	
1	L Station Road Not working – dead short in the gear within the lantern. Lantern also vandalised. Lantern fibreglass is heavily broken down.	Replace lantern	
1	M Station Road Vandalised lantern with split diffuser. Lantern fibreglass is heavily broken down.	Replace lantern	
1	N Station Road New pole box required – heavily corroded with holes in it. Vandalised SRL diffuser. Lantern fibreglass is heavily broken down.	Replace pole box and lantern	
1	B Stoney Lane Non-working vandalised Windsor lantern on wall mounted bracket. No Secondary Isolation. Impossible to reach the gear tray from a ladder. The frog base is heavily corroded. Looks like a pyro supply to the pole box, no idea where it originates from though, possibly one of the buildings to the right. The Earth cable is only wrapped around it instead of being clamped.	Replace lantern with SL10 + Earthing	
1	D Stoney Lane Day burning Windsor lantern (ladder job on footpath) Tails upgrade required, column has no Earth path to it. The column is leaning but is solid in the ground, the old Waters Windsor lantern is leaning too.	Replace lantern with SL10 + Earthing	
1	A Summerheath Road Pruning required to reach and work on this pole box/ lantern. New pole box required – very corroded with holes in it. One of the lantern diffuser clips is missing. Note there is a live nest nearby so nothing can be done on this until nesting season is over.	Replace pole box & lantern + pruning	
1	C Summerheath Road New pole box required – broken door hinges. No Secondary Isolation – no room in the existing clock box. No Neutral block just a connector block. No Earth path to the pole box.	Replace pole box and lantern	
1	D Summerheath Road New pole box required – broken door hinges, corroded lock catch and holes in the pole box itself.	Replace pole box and lantern	
1	E Summerheath Road New pole box required. Pole box door hinges are broken. Secondary Isolation is too large for the box, it is unfixed and positioned upside down to get the door shut.	Replace pole box and lantern	
1	I Summerheath Road Broken BICC Mains Cut-out fuse carrier. Secondary Isolation upgrade required. Tails upgrade required.	Replace lantern & fuse carrier	
1	A The Avenue Big ants' nest inside the column needs digging out and removing and ant powder then used to fill the column.	Remove ants' nest and treat	

Tender Specification - Pricing Schedule

Category	Location / Defect Details	Required Works	Price (£ ex VAT)
1	B The Avenue Broken door swivel lock – old Cast Iron door -not repairable.	Secure door with Tespar band	
1	D The Avenue Broken door swivel lock – old Cast Iron door - not repairable.	Secure door with Tespar band	
1	D The Drive Broken Mains Cut Out. Cast iron column door is cracked and has no lock – neither are replaceable. Very low blank/faded sign needs removing.	Replace column	
1	F The Drive Big ants nest inside the column needs digging out and removing and ant powder used. Old faded sign needs removing.	Remove ants' nest and treat + remove sign	
1	B The Lowlands No Secondary isolation. Column Earth has snapped and also needs upgrading, no Earth path to the column at present. Lantern fibreglass is heavily broken down. Badly discoloured diffuser. Water ingress in the photocell.	Replace lantern + Earthing	
1	D The Lowlands The column door is corroded with holes in it. No Secondary Isolation. Column Earth upgrade required. Bent swan neck.	Replace lantern, Swan Neck Bracket & door	
1	A The Mount Day burning lantern.	Replace photocell	
1	E Western Road Very corroded pole box, it is full of holes and is also split.	Replace pole box and lantern	
1	F Western Road There is no Earth path to the pole box. The pole box has broken door hinges. The cables run through the top of the pole box which is also split, it is dry at present.	Replace pole box and lantern	
1	I Western Road New column required – corrosion I the base with holes in it.	Replace column	
1	J Western Road New column required – corroded at the base with a hole in it. Secondary isolation upgrade required. Pruning required.	Replace column + pruning	
1	K Western Road Vandalised SRL diffuser. Lantern fibreglass is heavily broken down.	Replace lantern	
1	L Western Road The pole bracket is loose and angled downwards as a result, it needs new longer bolts to fix it back in place. This has two pole boxes with unusual wiring with two Mains Cut Outs and a Charles Endirect Secondary Isolation unit.	Reconfigure pole boxes, refix pole bracket and replace lantern + pruning	
1	N Western Road New pole box required. Broken door hinges. Pole box has no Earth path to it. Secondary Isolation unit is damaged.	Replace pole box and lantern	
1	O Western Road Missing pole box door, cut down paint tub lid has been set over it with lots of tape holding it in place. The pole box has no Earth path to it. Pruning required. The pole is set quite a way back I the front garden so quite a distance from the road.	Replace pole box and install long arm pole bracket, replace lantern + pruning	
1	A Windsor Road New column required – heavily corroded base with holes in it. Secondary isolation upgrade required. Old faded sign needs removing.	Replace column	
1	B Windsor Road Heavily corroded pole box and the door does not close or lock. No Secondary isolation. The Mains supply cable is draped over the pole box and has a split in it – requires a new pole box fitted ready along with a new light before reporting it.	Replace pole box and lantern	
1	C Windsor Road New column required – corroded with a hole in the base.	Replace column	
1	A Woodlands Close Secondary isolation upgrade required, tails upgrade required. Column has thinned and corroded below the door entry hole, the lock and recess area have rusted away – the door is cable ties on and is not replaceable. Lots of heavy rust falls down from up inside the column on test. SRL lantern fibreglass is heavily broken down.	Replace column	
1	B Woodlands Close New column required – corroded below the door entry hole with a hole in it. There is also a large hole at the joint between the	Replace column	

Category	Location / Defect Details	Required Works	Price (£ ex VAT)
	column and Swan Neck bracket. The Column door is missing and a plastic cover is cable tied in place.		
1	C Woodlands Close New column required – corroded with a hole in the base and very thin below the door entry hole. The column is also full of water. Secondary Isolation upgrade required, tails upgrade required. The column door is also heavily corroded.	Replace column	
1	A Woodside Way This pole has two pole boxes, both have broken locks. Broken door hinges too. The Secondary isolation is in pieces because it is the wrong size for the pole box it is in. Tails upgrade required. Neither pole box has an Earth path to it. These are joined pole boxes, with the Mains in the lower one so cannot remove one. They need drilling out and the locks replacing. Note to work on this I have to park across the entrance to the close and the entrance is on a 60mph road, anything wanting to turn in has to sit in the inside live lane and any accident will be on us. The TC will need to arrange a no access in/out timeslot with residents for us to safely work here.	Replace lantern, pole box hinges and door locks	
1	B Woodside Way New pole box required – broken door and broken hinges. Pole box has no Earth path to it. Secondary isolation cover is missing.	Replace pole box and lantern	
2	B Abbey Path Pruning required. The photocell has water ingress. SRL lantern fibreglass is heavily broken down. The diffuser is badly discoloured.	Replace lantern + pruning	
2	D Acorn Green Secondary isolation upgrade required.	Replace lantern	
2	3 Amberstone Wooden pole needs clearing of Ivy.	Pruning	
2	B Amberstone View Pruning required. (15 mins) The column is very solid in the ground but has been nudged and there is a deep gap around it in the tarmac – this need filling with tarmac to prevent water pooling next to the column below ground.	Dig out around base and re-Tarmac + pruning	
2	C Amberstone View Old sign brackets left on the column need removing. Heavily corroded swive lock column door – no spares.	Replace door and remove brackets	
2	E Amberstone View No Secondary Isolation.	Replace lantern	
2	A Ashford Close Lantern starting to fail, one of the LED sections has dropped out.	Replace lantern	
2	B Ashford Close Secondary isolation upgrade required. Column Earth upgrade required.	Replace lantern	
2	A Arundel Close Tails upgrade required.	Replace lantern	
2	B Arundel Close Secondary isolation upgrade required, tails upgrade required. Old faded sign needs removing from the column.	Replace lantern + remove sign	
2	A Battle Crescent Dented 5m square corner Fabrikat door. Water ingress in the photocell. SRL lantern fibreglass is heavily broken down. The diffuser is badly discoloured.	Replace lantern + door	
2	C Battle Crescent SRL lantern fibreglass is heavily broken down. The diffuser is badly discoloured.	Replace lantern	
2	E Battle Crescent Water ingress in the photocell. SRL lantern fibreglass is heavily broken down. The diffuser is badly discoloured.	Replace lantern	
2	B Bell Banks Road Secondary Isolation cover missing because it is too big. Pole box has no Earth path to it. Wooden pole needs clearing of Ivy.	Replace Secondary Isolation unit + Earthing + pruning	
2	C Bell Banks Road Pole box has a broken hinge and the lock catches are rusting away. No Secondary isolation.	Replace lantern + pole box	
2	F Bell Banks Road Loose in the ground and leaning two ways. (PHB RTV) Dented column door with caved in crumple zone, Mains Cut Out and	RTV column + replace door & photocell	

Tender Specification - Pricing Schedule

Category	Location / Defect Details	Required Works	Price (£ ex VAT)
	Secondary Isolation undamaged at present – 5m square corner door required. Water ingress in the photocell.		
2	A Bexley Close No Secondary Isolation, column has no Earth path to it.	Replace lantern + Earthing	
2	B Blossom Walk Column is slightly thin below the door entry hole and has water in the base of the column but it is solid at present. Secondary Isolation upgrade required.	Replace lantern	
2	F Bramble Drive Column leaning two ways, solid in the ground. Some corrosion at ground level but the column is solid at present.	RTV	
2	G Bramble Drive Earth block needs fixing back, currently floating in the column. Pruning required.	Earthing & pruning	
2	H Bramble Drive Column leaning two ways, solid in the ground.	RTV	
2	R Bramble Drive Some deep corrosion at ground level but the column is solid at present. Old fibre advice works sign needs removing.	Replace column	
2	A Caburn Way Secondary Isolation upgrade required. Lantern fibreglass is heavily broken down.	Replace lantern	
2	B Cackleberry Close Leaning column that is solid in the ground.	Replace column	
2	D Cackleberry Close Column has a corroded base – solid at present, probably 2 years left.	Replace column	
2	E Cackleberry Close Solid column has surface corrosion on the base outside, however below ground inside the column is heavily corroded and it is full of water.	Replace column	
2	C Cameron Close No Secondary Isolation. Pole box has no Earth path to it.	Replace lantern	
2	A Chestnut Close Concrete column with horizontal crack above the door going all the way around the column. there are further cracks at the top of the column around the neck joint, there are also loose lumps taped in place there.	Replace column	
2	B Chestnut Close Concrete column door has no Earth path to it. The Earth to the lantern has snapped. Water ingress in the photocell. The lantern Fibreglass is heavily broken down.	Replace lantern + Earthing	
2	A Coldthorn Lane Pruning required.	Pruning	
2	E Cornfield Green Old faded blank sign needs removing.	Remove sign	
2	G Cornfield Green Secondary Isolation upgrade required, tails upgrade required,	Replace lantern	
2	A Derwent Close Corroded Swan Neck bracket joint, no holes yet. Secondary Isolation upgrade required, tails upgrade required. Old faded blank sign needs removing.	Replace lantern + remove sign	
2	C Derwent Close Secondary Isolation upgrade required, tails upgrade required. Lantern is day burning. Swan Neck bracket joint is heavily corroded but no hole yet.	Replace lantern	
2	E Derwent Close Secondary Isolation upgrade required, tails upgrade required. Swan Neck bracket joint is heavily corroded but no hole yet.	Replace lantern	
2	H Derwent Close Secondary Isolation upgrade required, tails upgrade required.	Replace lantern	
2	D Ditchling Way Pruning required.	Pruning	
2	E Ditchling Way Secondary Isolation upgrade required, tails upgrade required.	Replace lantern	
2	F Ditching Way Pruning required	Pruning	

Tender Specification - Pricing Schedule

Category	Location / Defect Details	Required Works	Price (£ ex VAT)
2	B Douglas Close Lantern starting to fail – 1 LED section has stopped working.	Replace lantern	
2	A Downsvie Way – Pruning required, footpath column.	Pruning	
2	D Eastwell Place Secondary Isolation upgrade required, tails upgrade required. The column has no Earth path to it.	Replace lantern	
2	A Elm Green (Harmers Hay Road) Secondary Isolation upgrade required, tails upgrade required.	Replace lantern	
2	D Elm Green (Harmers Hay Road) Secondary Isolation upgrade required, tails upgrade required.	Replace lantern	
2	B Elmsdown Place Old sign strap needs removing from the column.	Remove sign	
2	C Elmsdown Place Column door is corroded around the screw in tri head bolt recess.	Replace door	
2	F Ersham Road No Secondary Isolation. Earth strap needs drilling and bolting to the side of the pole box.	Replace lantern + Earthing	
2	H Ersham Road Lantern fibreglass is heavily broken down.	Replace lantern	
2	I Ersham Road Secondary Isolation upgrade required. Pruning required.	Replace lantern + pruning	
2	O Ersham Road Pole box hinges are broken and the door completely detaches. No Secondary Isolation. The pole box has no Earth path to it.	Replace pole box and lantern	
2	A Ersham Way Secondary Isolation upgrade required, existing cover does not fit. The Axia lantern has 4 of the 16 LEDS not working.	Replace lantern	
2	B Falcon Way Column has surface corrosion on the base but is solid at present. Secondary Isolation upgrade required. Tails upgrade required. The column door is corroded with holes in it.	Replace column	
2	A Featherbed Lane Pole box has no Earth path to it.	Earthing	
2	B Fern Green Secondary isolation upgrade required, tails upgrade required.	Replace lantern	
2	A Fir Tree Close Tails upgrade required. Column has no Earth path to it.	Replace lantern	
2	C Fir Tree Close Pruning required	Pruning	
2	B Garfield Road There is no Earth path to the column.	Earthing	
2	C Garfield Road Secondary isolation upgrade required.	Replace lantern	
2	B Gordon Road No Secondary Isolation.	Replace lantern	
2	C Gordon Road Loose column door Earth. Old faded sign needs removing.	Earthing + remove sign	
2	A Harebeating Close Old Secondary Isolation base left in the column needs removing.	Remove base	
2	A Harebeating Crescent Secondary Isolation upgrade required. Tails upgrade required.	Replace lantern	
2	E Harebeating Crescent Secondary isolation upgrade required, tails upgrade required. Pruning required.	Replace lantern + pruning	
2	F Harebeating Crescent The column is heavily corroded and thinning below the door entry hole. The column door is corroded with holes in it. (no replacements) Secondary isolation upgrade required, tails upgrade required.	Replace column	
2	G Harebeating Crescent No Secondary Isolation.	Replace lantern	
2	A Harebeating Drive Future column warning – dark penetrating corrosion on the base, it is a warning only as it is solid at present with possibly	Replace column	

Category	Location / Defect Details	Required Works	Price (£ ex VAT)
	another year or two left before holes appear. Old faded sign needs removing.		
2	B Harebeating Drive Secondary isolation upgrade required, tails upgrade required. Broken gear tray/diffuser hinge point. SRL lantern fibreglass is heavily broken down. The diffuser is badly discoloured. Old faded blank sign needs removing.	Replace lantern + remove sign	
2	C Harebeating Drive Secondary isolation upgrade required, tails upgrade required. Future column warning – heavy dark penetrating corrosion on the base, it is a warning only as it is solid at present with possibly another 2 years left before holes appear. Old faded sign needs removing. Lantern fibreglass is heavily broken down.	Replace column	
2	D Harebeating Drive Secondary isolation upgrade required. Broken Mains Cut-out. Future column warning – very heavy dark penetrating corrosion on the base, it is a warning only as it is solid at present with possibly another year left before holes appear. Broken gear tray/diffuser hinge point. SRL lantern fibreglass is heavily broken down. The diffuser is heavily discoloured.	Replace column	
2	F Harebeating Drive Broken concrete ring around the column, the remaining pieces of concrete need removing and disposing of. The column is solid in place and a new ring is not required.	Remove loose concrete and dispose	
2	I Harebeating Drive Secondary isolation upgrade required, tails upgrade required. The column door is corroded with holes in it (no spares) The column joint with the Swan Neck bracket is corroded but is solid at present with no holes.	Replace column	
2	J Harebeating Drive Future column warning – dark penetrating corrosion on the base, it is a warning only as it is solid at present. The column joint with the Swan Neck bracket is heavily corroded but is solid at present with no holes.	Replace column	
2	K Harebeating Drive Secondary isolation upgrade required, tails upgrade required.	Replace lantern	
2	L Harebeating Drive Bent column shaft, the base is solid in the ground with no movement at all. The column joint with the swan neck is heavily corroded with holes in it.	Replace column	
2	A Harebeating Gardens Secondary isolation upgrade required, tails upgrade required.	Replace lantern	
2	A Harebeating Lane Pole box has no Earth path to it. The new pole bracket has been fitted upside down so is sloped downwards, as a result the cable is fed through the top of the bracket and is chaffing. The Mains supply cable is hanging loose from the pole. The lantern cable is also hanging loose from the pole.	Refit pole bracket, clip loose cabling + Earthing	
2	B Harebeating Lane Pole box has no Earth path to it.	Earthing	
2	J Hawks Road Old faded blank sign needs removing.	Remove sign	
2	M Hawks Road Wooden pole needs clearing of Ivy.	Pruning	
2	P Hawks Road Secondary isolation upgrade required. Lantern fibreglass is heavily broken down.	Replace lantern	
2	A Hawkstown Close Secondary isolation upgrade required, tails upgrade required. The column door is dented in the crumple zone – 5m round corner door required.	Replace lantern + door	

Tender Specification - Pricing Schedule

Category	Location / Defect Details	Required Works	Price (£ ex VAT)
2	A Hawkstown Crescent Secondary isolation upgrade required, tails upgrade required. SRL lantern fibreglass is heavily broken down. The diffuser is badly discoloured.	Replace lantern	
2	E Hawkstown Crescent Tails upgrade required. SRL lantern fibreglass is heavily broken down. The diffuser is badly discoloured.	Replace lantern	
2	F Hawkstown Crescent Secondary Isolation upgrade required. Tails upgrade required. The column joint with the Swan Neck bracket is corroded but solid at present.	Replace lantern	
2	A Hawkstown Gardens Secondary isolation upgrade required, tails upgrade required. SRL lantern fibreglass is heavily broken down. The diffuser is badly discoloured. The column door is corroded with holes in it (no spares).	Replace lantern & door	
2	D Hawkstown Gardens The column joint with the Swan Neck bracket is starting to corrode but is solid at present with no holes.	Replace lantern & Swan Neck bracket	
2	C Hawkstown View There is no Earth path to the column, the Earth cable is floating in the column unconnected. Earth block required.	Earthing	
2	C Hawkswood Drive Lantern failing, only 3 of the 4 LED sections are working. Secondary isolation upgrade required, tails upgrade required. New 5m square corner door required.	Replace lantern + door	
2	D Hawkswood Drive Concrete column leaning two ways but solid in the ground. The Earth to the concrete column door has been cut away and needs replacing. Broken column door with missing corner and no drop lock. Secondary Isolation upgrade required.	Replace column	
2	I Hawkswood Drive Secondary Isolation unit is not fixed and is sat on the bottom of the pole box. Pole box has no Earth path to it. Wooden pole needs clearing of Ivy.	Replace lantern + pruning	
2	C Hawthylands Crescent Very solid column with surface corrosion at the base. Old sign strap needs removing.	Remove sign	
2	D Hawthylands Crescent Very solid column with surface corrosion at the base. Secondary Isolation upgrade required, tails upgrade required. Corroded column door with holes in it (no spares).	Replace lantern & door	
2	E Hawthylands Crescent Column going soft, wet column inside below ground level too and full of water. Lantern is failing with three LED sections not working.	Replace column	
2	G Hawthylands Crescent Secondary isolation upgrade required. The column is solid at present, however it is going thin on one side of the door entry hole. Lantern fibreglass is heavily broken down. Badly discoloured diffuser.	Replace column	
2	B Hawthylands Drive Future advisory for the column – very thin below the door entry hole. The base is also corroded but is solid at present.	Replace column	
2	A Hawthylands Road Secondary isolation upgrade required, tails upgrade required. New door required, it is corroded with holes in it.	Replace lantern + door	
2	D Hawthylands Road Failing lantern only 3 of the 4 LED sections work. Missing door- swivel butterfly type (we have no spares, will if columns are replaced here) Corroded base – surface only and column solid at present.	Replace lantern	
2	F Hawthylands Road Column has a corroded base and is soft and malleable – no holes yet but will only last a year or so.	Replace column	
2	I Hawthylands Road Failed lantern, only three quarters of the LEDs are attempting to light up but failing with just a faint glow. The bottom of the door has corroded away. Heavily corroded base, very soft column but no	Replace column	

Category	Location / Defect Details	Required Works	Price (£ ex VAT)
	holes in it. The column is also very thin below the door entry hole. There is corrosion inside the column too.		
2	K Hawthylands Road Corroded base – surface only and column solid at present, also very wet inside the column. The door has corroded on the bottom and the locator lug is missing, fitted upside down and cable tied in place as a result (swivel butterfly lock type we have no spares for, replaced columns here may provide some) Old faded blank sign needs removing.	Replace column	
2	N Hawthylands Road Solid column on the outside, very wet and corroding inside – couple of years left yet. Leaning column. Pruning required.	Replace column + pruning	
2	Q Hawthylands Road Secondary Isolation upgrade required. Solid column on the outside, full of water and heavily corroded inside below ground level.	Replace column	
2	R Hawthylands Road Pruning required.	Pruning	
2	A Hayland Green Secondary Isolation upgrade required, tails upgrade required. Slightly buckled column, upright and solid, ok – note only.	Replace lantern	
2	D Hayland Green (this is possibly one of the others around the greens) Secondary Isolation upgrade required, tails upgrade required.	Replace lantern	
2	D Hayland Green Failing lantern one of the four LED sections is out. Secondary Isolation upgrade required, tails upgrade required.	Replace lantern	
2	B Ingrams Way Missing column door. Lantern fibreglass is heavily broken down. Heavily discoloured diffuser.	Replace lantern	
2	D Ingrams Way Secondary Isolation upgrade required, tails upgrade required. Column is leaning two ways, solid in the ground.	Replace lantern + RTV	
2	M Ingrams Way Pruning required.	Pruning	
2	A Ilex Green Secondary Isolation upgrade required, tails upgrade required.	Replace lantern	
2	B Jasmine Green Secondary Isolation upgrade required, tails upgrade required. Water in the base of the column, note only it is solid at present.	Replace lantern	
2	D Knights Garden Broken Secondary Isolation unit needs replacing – was fitted too high and the door lock has been clamping onto it. Leaning and a little loose in the tarmac.	Replace lantern + RTV	
2	A Laburnum Green (Harmers Hay Road) Column is set into the ground virtually to the bottom of the door entry hole. The column is full of water to the bottom of the door as a result. Column is very corroded and will soon need replacing.	Replace column	
2	B Laburnum Green (Harmers Hay Road) Secondary Isolation upgrade required, tails upgrade required.	Replace lantern	
2	B Lansdowne Drive surface corrosion at the base of the column – solid at present, however the column is thinning below the door entrance hole.	Replace column	
2	A Lansdowne Crescent Broken sign needs removing.	Remove sign	
2	C Lansdowne Road Pruning required.	Pruning	
2	E Lansdowne Road Old sign needs removing form the column.	Remove sign	
2	C Lansdowne Way Old sign strap needs removing.	Remove sign	
2	D Lansdowne Way Old sign strap needs removing. Old Faded blank sign needs removing.	Remove signs	
2	E Lansdowne Way Old Faded blank sign needs removing.	Remove sign	
2	A Lepeland Heavily corroded Swan Neck bracket joint – no holes yet. The Earthing needs reconfiguring and the column Earth is very undersized.	Replace lantern & Swan Neck Bracket	

Category	Location / Defect Details	Required Works	Price (£ ex VAT)
2	E London Road (South) Secondary Isolation upgrade required, tails upgrade required.	Replace lantern	
2	I London Road (South) No Secondary Isolation. Pole box has no Earth path to it. Pole box lock is missing – requires new bolt and wing nut. Pruning and Wooden pole Ivy clearance required.	Replace lantern & missing bolt + pruning	
2	B London Road (North) No Secondary isolation. The old Earth bolt sticking out the side of the column is causing the door to sit off centre and needs cutting away and then a new Earth bolt fitted elsewhere.	Replace lantern + Earthing	
2	D London Road (North) No Secondary isolation. The column has surface corrosion on the bottom but is solid.	Replace lantern	
2	F London Road (North) The column is thin below the door entry hole but has no holes in it yet. The column door is corroded with holes in it. No secondary Isolation.	Replace column	
2	G London Road (North) Old metal clamp remains need removing from the column.	Remove clamp	
2	K London Road (North) The base of the column has surface corrosion but is very solid. Old faded sign needs removing from the column.	Remove sign	
2	L London Road (North) No Secondary Isolation. Earth path to the column requires upgrade.	Replace lantern	
2	E London Road Cuckoo Trail to The Cedars Tails upgrade required, requires a dual fused secondary or Bill SL3D2 to resolve the in/out supply and remove the old relay base. Pruning required.	Replace lantern + pruning	
2	A Manor Park Close Lots of water in the base of the column below ground. The column is solid outside but is corroding inside below ground level.	Replace column	
2	C Manor Park Road The column door is corroded along the top locator edge section, no holes at present. No Secondary isolation. Earth path to the column requires upgrading.	Replace lantern	
2	A Meadow Road Secondary Isolation upgrade required, tails upgrade required. The Mains Cut Out looks like a panel is missing and tar is coming out of it. Old faded blank sign needs removing.	Replace lantern + remove sign	
2	C Meadow Road Secondary Isolation upgrade required, tails upgrade required.	Replace lantern	
2	D Mill Road Secondary Isolation cover is missing because this model is too big for the pole box.	Replace Secondary Isolation unit	
2	I Mill Road New pole box required – it is corroded with holes in it.	Replace pole box and lantern	
2	L Mill Road No Earth path to the pole box. Pruning Required.	Earthing and pruning	
2	Q Mill Road Secondary Isolation upgrade required.	Replace lantern	
2	A Milland Road Secondary Isolation upgrade required, tails upgrade required. (The Secondary is wired the wrong way round)	Replace lantern	
2	A New Barn Close Leaning heavily and very loose in the ground.	RTV	
2	B New Barn Close Leaning heavily and very loose in the ground. Secondary Isolation upgrade required.	Replace lantern + RTV	
2	6 New Road No Secondary Isolation. Pruning and wooden pole Ivy clearance required.	Replace lantern + pruning	
2	7 New Road Wooden pole Ivy clearance required.	Pruning	
2	10 New Road No Secondary Isolation.	Replace lantern	
2	1 Noades Lane Secondary Isolation upgrade required. Pole box has no Earth path to it.	Replace lantern	

Tender Specification - Pricing Schedule

Category	Location / Defect Details	Required Works	Price (£ ex VAT)
2	A Oak Tree Way Secondary Isolation upgrade required, tails upgrade required.	Replace lantern	
2	B Oak Tree Way SRL lantern fibreglass is heavily broken down. The diffuser is heavily discoloured.	Replace lantern	
2	C Oak Tree Way Secondary Isolation upgrade required, tails upgrade required. The column is full of water below ground level and is going thin below the door entry hole. Column is leaning but is solid in the ground – this will be resolved when it is replaced.	Replace column	
2	A Oaklands Way The column is very soft and malleable below the door entrance hole and is caved in. Secondary Isolation upgrade required.	Replace column	
2	B Oaklands Way The column is very soft and malleable, it is heavily corroded below ground on the inside and the column is also full of water.	Replace column	
2	B Old Orchard Place Secondary Isolation upgrade required.	Replace lantern	
2	D Old Orchard Place Earth bolt has detached from the column and needs replacing. Secondary Isolation upgrade required. Tails upgrade required.	Replace lantern + Earthing	
2	F Old Orchard Place Secondary Isolation upgrade required.	Replace lantern	
2	G Old Orchard Place Pruning required.	Pruning	
2	4 Old Road A new column has been installed next to the old wooden pole. The old pole box is still on the pole and needs removing.	Remove and dispose of old pole box	
2	A Park Close Column Earth upgrade required. Old Secondary isolation base needs removing. Lantern fibreglass is heavily broken down. Badly discoloured diffuser.	Replace lantern	
2	A Paul Close No Secondary Isolation.	Replace lantern	
2	C Paul Close No Secondary Isolation. The lantern fibreglass is heavily broken down. The diffuser is badly discoloured. Water ingress in the photocell.	Replace lantern	
2	D Paul Close Pruning Required.	Pruning	
2	E Paul Close There is no Earth path to the column. Column is bent and full of water, the backboard is disintegrating as a result. There is heavy corrosion inside the column.	Replace column	
2	A Quintin Close Secondary Isolation upgrade required, tails upgrade required.	Replace lantern	
2	B Robin Post Lane No Secondary Isolation.	Replace lantern	
2	B Sackville Road Secondary Isolation upgrade required. No Earth path to the pole box. Loose box because the fixing bolts need fully screwing home.	Replace lantern + Earthing	
2	A Sandbanks Close No Secondary Isolation.	Replace lantern	
2	A Sandbanks Grove Pruning required.	Pruning	
2	A Sandbanks Way Secondary Isolation upgrade required. Requires an ants nest to be dug out and the column powdered inside.	Replace lantern + Remove ants' nest and treat	
2	B Sandbanks Way Secondary Isolation upgrade required. Requires an ants nest to be dug out and the column powdered inside.	Replace lantern + Remove ants' nest and treat	
2	D Sandbanks Way Secondary Isolation upgrade required.	Replace lantern	
2	G Sandbanks Way Secondary Isolation upgrade required.	Replace lantern	
2	H Sandbanks Way Secondary Isolation upgrade required.	Replace lantern	
2	I Sandbanks Way Lantern fibreglass is heavily broken down. Heavily discoloured diffuser.	Replace lantern	

Tender Specification - Pricing Schedule

Category	Location / Defect Details	Required Works	Price (£ ex VAT)
2	J Sandbanks Way Lantern fibreglass is heavily broken down. Heavily discoloured diffuser.	Replace lantern	
2	A Southerden Close Secondary isolation upgrade required, the existing cover is missing too. Column Earth upgrade required. Pruning required.	Replace lantern + pruning	
2	B St Wilfrids Green Secondary Isolation upgrade required. Old time switch needs removing. There is no Earth path to the column. Residents asked us to move the Swan Neck bracket 180 degrees and face the other way. There's a lot of foliage on the turning island and less behind than in front. Missing swivel lock on the cast iron column door – not replaceable.	Replace lantern + adjust bracket	
2	A Station Road Pruning required. Missing lantern clip.	Replace lantern + pruning	
2	C Station Road Pruning required.	Pruning	
2	E Station Road Pruning required.	Pruning	
2	C Stoney Lane Secondary isolation upgrade required. The cover of the existing one is also missing.	Replace lantern with SL10	
2	E Stoney Lane Secondary isolation upgrade required. There is no Earth path to the column. The lamp holder is hanging by the supply cables. This is a very poor condition Windsor lantern with cracked perspex from vandalism. Part of the hinged door window has broken and the framework is bent and sticking out too. Cannot work on this gear tray from a ladder it is too dangerous.	Replace lantern with SL10	
2	B Summerheath Road Pole box has no Earth path to it. No room with current oversized Secondary Isolation that has its cover missing.	Replace Secondary Isolation unit + Earthing	
2	G Summerheath Road No Secondary Isolation. Pole box has no Earth path to it.	Replace lantern	
2	H Summerheath Road Tails upgrade required.	Replace lantern	
2	J Summerheath Road Pruning required.	Pruning	
2	C The Avenue Secondary isolation upgrade required. No Earth path to the column, the cable is just floating unconnected. The column needs drilling out and an Earth bolt fitted.	Replace lantern + Earthing	
2	E The Avenue Secondary isolation upgrade required. Old sign strap left on the column needs removing.	Replace lantern + remove sign	
2	F The Avenue Secondary isolation upgrade required. Old faded blank sign on the column needs removing. The photocell has a lot of water inside it.	Replace lantern + remove sign	
2	B The Drive Secondary isolation upgrade required.	Replace lantern	
2	C The Drive No Secondary Isolation.	Replace lantern	
2	A The Holt Secondary Isolation upgrade required, tails upgrade required. Old sign strap left on the column needs removing.	Replace lantern + remove sign	
2	B The Holt Secondary Isolation upgrade required, tails upgrade required.	Replace lantern	
2	A The Lowlands Column Earth upgrade required. The door catch plate section is corroding badly. Lantern fibreglass is heavily broken down.	Replace lantern + Earthing	
2	C The Lowlands Water ingress in the photocell. Lantern fibreglass is heavily broken down.	Replace lantern + Earthing	
2	E The Lowlands Secondary isolation upgrade required.	Replace lantern	
2	B The Mount Secondary Isolation upgrade required. Missing column Earth nut, the cable simply sits on the bolt. Galvanised column is full of water below ground. Broken swivel door lock, the door is cable tied in place.	Replace lantern + door	
2	D The Mount Secondary Isolation upgrade required, tails upgrade required.	Replace lantern	

Tender Specification - Pricing Schedule

Category	Location / Defect Details	Required Works	Price (£ ex VAT)
2	E The Mount Secondary Isolation upgrade required, tails upgrade required. The Earth on the column is not fixed back. Missing door swivel lock, the door is cable tied in place.	Replace lantern + door	
2	F The Mount Secondary Isolation upgrade required, tails upgrade required.	Replace lantern	
2	H The Mount No Secondary Isolation. In and out Mains supply cables so Earth cable in connector blocks.	Replace lantern + earthing	
2	I The Mount Secondary Isolation upgrade required. Door swivel lock is missing. Earths just tied together.	Replace lantern + door	
2	B Victoria Road This is a disconnected wall bracket lantern with a new galvanised column installed next to it. This situation needs tidying up as it is unsightly.	Remove lantern bracket and box + disposal	
2	A Western Road Secondary Isolation upgrade required.	Replace lantern	
2	B Western Road Secondary Isolation upgrade required. Tails upgrade required. There is no Earth path to the column. Broken Mains Cut-out fuse holder.	Replace lantern & fuse carrier	
2	D Western Road There is no Earth path to the pole box. The corner of the door is broken.	Replace lantern	
2	G Western Road Secondary Isolation upgrade required. The column is corroded as ground level but solid at present – note only. Old sign strap need removing from the column.	Replace lantern + remove sign	
2	H Western Road There is no Earth path to the pole box.	Earthing	
2	D Windsor Road Both old faded blank signs need removing.	Remove signs	
2	D Woodlands Close New column required in the future, it is malleable below the door entrance hole and dented but has no holes and is solid at present, however the door locating bars are corroded and coming away from the column. Vandalised lantern with splits in the Sox Beta 5 diffuser. Secondary isolation upgrade required.	Replace column	
	B Cameron Close Not working. I cannot reach this off a ladder, footpath column. Looks like a new wooden pole, so possibly was transferred over and fitted too high in the process. There's enough spare Mains cable to suggest that anyway. The pole box lock bolt has been cut through to allow the door to open, which needs drilling out and replacing. No Secondary Isolation – no room. Pole box has no Earth path to it. Currently with UKPN to resolve height issues.		
Note Only	I Bramble Drive Lower cover is missing from the Mains Cut-out (Note Only)		
Note Only	B Hawthylands Crescent Relatively new painted galvanised column has water in the bottom. (Note Only)		
Note Only	G Hawthylands Road Corroded base – surface only and column solid at present. (Note Only)		
Note Only	H Hawthylands Road Column corroded at the base and below the door entry hole – surface only and column solid at present. (Note Only)		
Note Only	A Lansdowne Drive Surface corrosion at the base of the column – solid at present. Corrosion at the Swan Neck bracket joint – solid at present. (Note Only)		
Note Only	H London Road Cuckoo Trail to The Cedars Broken Mains Cut-out. (Note Only)		
Note Only	A Manor Park Road The column door is corroded along the top locator edge section, no holes at present. (Note Only)		

Tender Specification - Pricing Schedule

Category	Location / Defect Details	Required Works	Price (£ ex VAT)
Note Only	A North Heath Close Corrosion at the base of the column – surface only. (Note Only)		
Note Only	A Nursery Path surface corrosion on the base of the column -very solid at present. (Note Only)		
	C The Mount Fence posts are tied to the column for stability. HTC to advise if ties are to be removed.		