

STRATEGY COMMITTEE

AGENDA

NOTICE IS HEREBY GIVEN OF a meeting of the STRATEGY COMMITTEE to be held in the Fleur de Lys Council Chambers, Market Square, Hailsham

Monday 10th July 2023 at 7.00 p.m.

1. Public Forum

(No more than 15 Minutes)

2. Apologies for Absence

To receive apologies for absence of appointed members.

3. **Declarations of Interest**

To receive notice of declarations of personal or prejudicial interests in respect of items on this agenda.

4. <u>Minutes of Previous Meeting – Assets Management Committee</u>

To resolve that the Minutes of the Strategy Committee held on Monday 27th March 2023 may be confirmed as a correct record and signed by the Chairman.

5. Progress against the Town Council's Strategic Plan

To note progress against current priorities within the Hailsham Town Council Strategic Plan for 2022-2026

6. **Confidential Business**

To resolve that the press and public are excluded during the discussion on the next item of the agenda (7) as it concerns: The beginning of legal proceedings and the terms of tenders for contracts or negotiations (In accordance with the Council's Standing Orders No. 1E).

7 <u>Progress against the Town Council's Strategic Plan (Confidential</u> Items)

To note progress against current priorities (confidential items) within the Hailsham Town Council Strategic Plan for 2022-2026

8. **Maintenance Plan**

To discuss any activities within the Maintenance Plan

John Harrison

Committee Membership (The committee consists of the Chairs and Deputy Chairs of council and all Standing Committees):

Chair of Council & Chair of Planning &

Development Committee

Cllr Paul Holbrook

Deputy Chair of Council, Deputy Chair of Staffing Committee & Deputy Chair of

Communities Committee

Cllr Anne-Marie Ricketts

Chair of Assets Management Committee &

Chair of Neighbourhood Plan Committee

Cllr Mary Laxton

Deputy Chair of Assets Management

Committee

Cllr Kelly-Marie Blundell

Chair of Communities Committee Cllr Alexa Clarke

Chair of Finance, Budget & Resources

Committee

TBC

Deputy Chair of Finance, Budget &

Resources Committee

TBC

Deputy Chair of Planning & Development

Committee

Cllr Chris Bryant

Chair of Staffing Committee

Cllr Karen Nicholls

Solway Open Space					
	Mark Barriand	Ti	C+	Davids of Date	Completed
Signage	Work Required 2 new signs required	Timescale 2021	£500	Revised Date 2024	Completed
Fencing	New vehicle Gate to cover 5 metre gap	2021	£200	2024	
encing	New vehicle date to cover 3 metre gap	2020	1200	2024	
	Replace chain-link fence left of entrance 10 metre run	2020	£500	2024	
	Replace chain-link fence by garages 12 metre run	2020	£650	2024	
	, , , ,		Total	£1,850	
Stroma Gardens Playpark					
Play equipment					
Roundabout	Replace with toddler	2020	£2350 s/o		2023
Slide (wicksteed)	Replace with toddler	2020	£3300 s/o		2023
Swing (cradle) (2009)	Replace with toddler	2024	£1100 s/o		2023
Springer helicopter	Replace with toddler	2020	£700 s/o		2023
Springer (removed)	Replace with toddler	2020	£700 s/o		2023
Bench and Table	Replace	2024	£1800 s/o		2023
encing					
Front chestnut Fencing	Replace 22 metres	2023	£700s/o	2024	
	Replace 21 metres at 10 foot and 53 metres at 8 foot				
Right chain-link fence	security fence	2023	£5500s/o	2024	
	Replace 19 metres at 10 foot and 30 metres at 8 foot				
_eft chain-link fence	security fence	2023	£4200s/o	2024	
Bottom old farm fence	Replace 100m at 4 foot securing fencing		£2800s/o	2024	
Signage	New sign required	2021	£250	2024	2023
Rubbish Bin	Replace		£600s/o		2022
AND SHIP	першее	2024	Total	£14,050	2022
Quinnel Drive Playmark			iotai	14,030	
Quinnel Drive Playpark					
Play equipment					
All Hags	Devilere		caoca '		
Swing	Replace		£2000s/o		
pringers X 2	Replace		£1300s/o		
ilide + Multiplay unit	Replace		£12000s/o		
pinner	Replace		£7000s/o		
Metal Picnic Bench	Replace	2029	£1000s/o		
Metal Seats X 2	Replace	2029	£1200s/o		
Cycle Rack	Replace	2029	£500s/o		
Bin	Replace		£800s/o		
Wood Edging to safety bark	Replace 50metre of 8X2		£200s/o	2024	
Bark Chippings	Top Up	2020	£1,000	2024	
				2024	
iign	Replace	2029	£900s/o	£28	
Onon Space			Total	140	
Open Space	Paulana 24 markes - CC - C		C42CC '		
Chestnut Fencing	Replace 34 metre of fencing		£1200s/o	2024	
Post and Rail Fencing	Replace 60 metre of fencing		£1500s/o		
Close board Fencing	Replace 25metres of fencing	2023	£2200s/o	2024	
			Total	£4,900	
Grovelands Barn & Orchard Park					
	Entrance to site from Grovelands Road - replace post & rail				
encing	fence				
	3 rail fence 9metres	2029	£250s/o		
	Chain-link fence around barn compound - replace with				
	security fencing	2023	£15000+	2025	
	XXX metres				
	Close board fence from bridge to the side of Pitreavie Drive -				
	replace 16 metres	2021	£1400s/o		2022
Bridge	Orchard Park to Pitreavie Drive replace handrail	2021	£100	2025	
3 %	Replace bridge	2024	£400	2025	
Dovecot	Replace dovecot	2024	£700	removed	2022
Pond	Remove pond	2020	£500	2024	
Olid	Repair path by footpath into Cameroon Close (already	2020	E300	2024	
Poths		2040	CC 000		2022
Paths	priced)	2019	£6,000		2022
	Remove tarmac path adjacent to dog bin and vehicle gate to				
			£300		2022
	barn site	2020	2500		
	Cut back growth and dig out ditch between Dunbar Drive				
Ditch	Cut back growth and dig out ditch between Dunbar Drive and Sensory Garden	2020	£600	2024	
	Cut back growth and dig out ditch between Dunbar Drive and Sensory Garden Take down the extension to the main barn building that is	2019/2020	£600		
	Cut back growth and dig out ditch between Dunbar Drive and Sensory Garden			2024 2024	
Ditch Barn Building	Cut back growth and dig out ditch between Dunbar Drive and Sensory Garden Take down the extension to the main barn building that is	2019/2020	£600		
	Cut back growth and dig out ditch between Dunbar Drive and Sensory Garden Take down the extension to the main barn building that is not tied into the barn	2019/2020	£600		
Barn Building	Cut back growth and dig out ditch between Dunbar Drive and Sensory Garden Take down the extension to the main barn building that is not tied into the barn Reconfigure roof	2019/2020	£600		
Barn Building	Cut back growth and dig out ditch between Dunbar Drive and Sensory Garden Take down the extension to the main barn building that is not tied into the barn Reconfigure roof Dig out spoil and remove from site & clear overgrown	2019/2020	£600 £3,500 £2,000	2024 2023	
Barn Building Barn Compound	Cut back growth and dig out ditch between Dunbar Drive and Sensory Garden Take down the extension to the main barn building that is not tied into the barn Reconfigure roof Dig out spoil and remove from site & clear overgrown	2019/2020	£600 £3,500	2024	
arn Building arn Compound ameron Close Open Space	Cut back growth and dig out ditch between Dunbar Drive and Sensory Garden Take down the extension to the main barn building that is not tied into the barn Reconfigure roof Dig out spoil and remove from site & clear overgrown brambles etc	2019/2020 2022 2020	£600 £3,500 £2,000 Total	2024 2023	
Barn Building Barn Compound Cameron Close Open Space	Cut back growth and dig out ditch between Dunbar Drive and Sensory Garden Take down the extension to the main barn building that is not tied into the barn Reconfigure roof Dig out spoil and remove from site & clear overgrown	2019/2020 2022 2020	£600 £3,500 £2,000 Total £3500s/o	2024 2023 £30,150	
Barn Building Barn Compound Cameron Close Open Space Tence	Cut back growth and dig out ditch between Dunbar Drive and Sensory Garden Take down the extension to the main barn building that is not tied into the barn Reconfigure roof Dig out spoil and remove from site & clear overgrown brambles etc	2019/2020 2022 2020	£600 £3,500 £2,000 Total	2024 2023	
Barn Building Barn Compound Cameron Close Open Space Fence Cameron Close former Play Area	Cut back growth and dig out ditch between Dunbar Drive and Sensory Garden Take down the extension to the main barn building that is not tied into the barn Reconfigure roof Dig out spoil and remove from site & clear overgrown brambles etc Metal frame half log fence replace 115 metres	2019/2020 2022 2020 2027	£600 £3,500 £2,000 Total £3500s/o Total	2024 2023 £30,150	
Barn Building Barn Compound Cameron Close Open Space Fence Cameron Close former Play Area	Cut back growth and dig out ditch between Dunbar Drive and Sensory Garden Take down the extension to the main barn building that is not tied into the barn Reconfigure roof Dig out spoil and remove from site & clear overgrown brambles etc Metal frame half log fence replace 115 metres Metal frame half log fence on front replace 27 metres	2019/2020 2022 2020 2027 2027	£600 £3,500 £2,000 Total £3500s/o Total £1500s/o	2024 2023 £30,150	
Barn Building Barn Compound Cameron Close Open Space Fence Cameron Close former Play Area	Cut back growth and dig out ditch between Dunbar Drive and Sensory Garden Take down the extension to the main barn building that is not tied into the barn Reconfigure roof Dig out spoil and remove from site & clear overgrown brambles etc Metal frame half log fence replace 115 metres Metal frame half log fence on front replace 27 metres Picket fence replace 18 metres with chainlink	2019/2020 2022 2020 2027 2027 2027 2025	£600 £3,500 f2,000 Total £3500s/o Total £1500s/o £800s/o	2024 2023 £30,150	
Barn Building Barn Compound Cameron Close Open Space Fence Cameron Close former Play Area Fence	Cut back growth and dig out ditch between Dunbar Drive and Sensory Garden Take down the extension to the main barn building that is not tied into the barn Reconfigure roof Dig out spoil and remove from site & clear overgrown brambles etc Metal frame half log fence replace 115 metres Metal frame half log fence on front replace 27 metres Picket fence replace 18 metres with chainlink Picket fence around tree replace or remove 22metres	2019/2020 2022 2020 2027 2027 2027 2025 2020	£600 £3,500 f2,000 Total £3500s/o Total £1500s/o £800s/o £300	2024 2023 £30,150	
Barn Building Barn Compound Cameron Close Open Space Fence Cameron Close former Play Area Fence	Cut back growth and dig out ditch between Dunbar Drive and Sensory Garden Take down the extension to the main barn building that is not tied into the barn Reconfigure roof Dig out spoil and remove from site & clear overgrown brambles etc Metal frame half log fence replace 115 metres Metal frame half log fence on front replace 27 metres Picket fence replace 18 metres with chainlink	2019/2020 2022 2020 2027 2027 2027 2025	£600 £3,500 f2,000 Total £3500s/o Total £1500s/o £800s/o	2024 2023 £30,150	
Barn Building Barn Compound Cameron Close Open Space Fence Cameron Close former Play Area Fence	Cut back growth and dig out ditch between Dunbar Drive and Sensory Garden Take down the extension to the main barn building that is not tied into the barn Reconfigure roof Dig out spoil and remove from site & clear overgrown brambles etc Metal frame half log fence replace 115 metres Metal frame half log fence on front replace 27 metres Picket fence replace 18 metres with chainlink Picket fence around tree replace or remove 22metres	2019/2020 2022 2020 2027 2027 2027 2025 2020	£600 £3,500 f2,000 Total £3500s/o Total £1500s/o £800s/o £300	2024 2023 £30,150	
Barn Building Barn Compound Cameron Close Open Space Fence Cameron Close former Play Area Fence	Cut back growth and dig out ditch between Dunbar Drive and Sensory Garden Take down the extension to the main barn building that is not tied into the barn Reconfigure roof Dig out spoil and remove from site & clear overgrown brambles etc Metal frame half log fence replace 115 metres Metal frame half log fence on front replace 27 metres Picket fence replace 18 metres with chainlink Picket fence around tree replace or remove 22metres Field Gate replace 2 mono hinge gates replace with normal gates, as this is no	2019/2020 2022 2020 2027 2027 2027 2025 2020	£600 £3,500 f2,000 Total £3500s/o Total £1500s/o £800s/o £300	2024 2023 £30,150	
Barn Building Barn Compound Cameron Close Open Space Fence Cameron Close former Play Area Fence Gates	Cut back growth and dig out ditch between Dunbar Drive and Sensory Garden Take down the extension to the main barn building that is not tied into the barn Reconfigure roof Dig out spoil and remove from site & clear overgrown brambles etc Metal frame half log fence replace 115 metres Metal frame half log fence on front replace 27 metres Picket fence replace 18 metres with chainlink Picket fence around tree replace or remove 22metres Field Gate replace 2 mono hinge gates replace with normal gates, as this is no longer a play area	2019/2020 2022 2020 2027 2027 2025 2020 2025 2029	£600 £3,500 Total £3500s/o Total £1500s/o £800s/o £300 £500	2024 2023 £30,150	
Barn Building Barn Compound Cameron Close Open Space Fence Cameron Close former Play Area Fence Fence	Cut back growth and dig out ditch between Dunbar Drive and Sensory Garden Take down the extension to the main barn building that is not tied into the barn Reconfigure roof Dig out spoil and remove from site & clear overgrown brambles etc Metal frame half log fence replace 115 metres Metal frame half log fence on front replace 27 metres Picket fence replace 18 metres with chainlink Picket fence around tree replace or remove 22metres Field Gate replace 2 mono hinge gates replace with normal gates, as this is no longer a play area Replace	2019/2020 2022 2020 2027 2027 2025 2020 2025	£600 £3,500 £2,000 Total £3500s/o Total £1500s/o £800s/o £500 £2,000	2024 2023 £30,150	
Barn Building Barn Compound Cameron Close Open Space Fence Cameron Close former Play Area Fence Gates Insect hotel	Cut back growth and dig out ditch between Dunbar Drive and Sensory Garden Take down the extension to the main barn building that is not tied into the barn Reconfigure roof Dig out spoil and remove from site & clear overgrown brambles etc Metal frame half log fence replace 115 metres Metal frame half log fence on front replace 27 metres Picket fence replace 18 metres with chainlink Picket fence around tree replace or remove 22metres Field Gate replace 2 mono hinge gates replace with normal gates, as this is no longer a play area Replace Level out ground around tree or close off uneven surface	2019/2020 2022 2020 2027 2027 2025 2020 2025 2029 2025	£600 £3,500 £2,000 Total £3500s/o Total £1500s/o £800s/o £300 £500 £2,000	2024 2023 £30,150	2022
	Cut back growth and dig out ditch between Dunbar Drive and Sensory Garden Take down the extension to the main barn building that is not tied into the barn Reconfigure roof Dig out spoil and remove from site & clear overgrown brambles etc Metal frame half log fence replace 115 metres Metal frame half log fence on front replace 27 metres Picket fence replace 18 metres with chainlink Picket fence around tree replace or remove 22metres Field Gate replace 2 mono hinge gates replace with normal gates, as this is no longer a play area Replace	2019/2020 2022 2020 2027 2027 2025 2020 2025 2029	£600 £3,500 Total £3500s/o Total £1500s/o £800s/o £300 £2,000 £2,000 £2,000	2024 2023 £30,150 £3,500	
Barn Building Barn Compound Cameron Close Open Space Fence Cameron Close former Play Area Fence Gates Insect hotel Ground	Cut back growth and dig out ditch between Dunbar Drive and Sensory Garden Take down the extension to the main barn building that is not tied into the barn Reconfigure roof Dig out spoil and remove from site & clear overgrown brambles etc Metal frame half log fence replace 115 metres Metal frame half log fence on front replace 27 metres Picket fence replace 18 metres with chainlink Picket fence around tree replace or remove 22metres Field Gate replace 2 mono hinge gates replace with normal gates, as this is no longer a play area Replace Level out ground around tree or close off uneven surface	2019/2020 2022 2020 2027 2027 2025 2020 2025 2029 2025	£600 £3,500 £2,000 Total £3500s/o Total £1500s/o £800s/o £300 £500 £2,000	2024 2023 £30,150	2022
Barn Building Barn Compound Cameron Close Open Space Fence Cameron Close former Play Area Fence Gates Insect hotel Ground Ashburnham Place	Cut back growth and dig out ditch between Dunbar Drive and Sensory Garden Take down the extension to the main barn building that is not tied into the barn Reconfigure roof Dig out spoil and remove from site & clear overgrown brambles etc Metal frame half log fence replace 115 metres Metal frame half log fence on front replace 27 metres Picket fence replace 18 metres with chainlink Picket fence around tree replace or remove 22metres Field Gate replace 2 mono hinge gates replace with normal gates, as this is no longer a play area Replace Level out ground around tree or close off uneven surface around tree	2019/2020 2022 2020 2027 2027 2025 2020 2025 2029 2025	£600 £3,500 Total £3500s/o Total £1500s/o £800s/o £300 £2,000 £2,000 £2,000	2024 2023 £30,150 £3,500	2022
Barn Building Barn Compound Cameron Close Open Space Fence Cameron Close former Play Area Fence Gates Insect hotel Ground	Cut back growth and dig out ditch between Dunbar Drive and Sensory Garden Take down the extension to the main barn building that is not tied into the barn Reconfigure roof Dig out spoil and remove from site & clear overgrown brambles etc Metal frame half log fence replace 115 metres Metal frame half log fence on front replace 27 metres Picket fence replace 18 metres with chainlink Picket fence around tree replace or remove 22metres Field Gate replace 2 mono hinge gates replace with normal gates, as this is no longer a play area Replace Level out ground around tree or close off uneven surface	2019/2020 2022 2020 2027 2027 2025 2020 2025 2029 2025	£600 £3,500 Total £3500s/o Total £1500s/o £800s/o £300 £2,000 £2,000 £2,000	2024 2023 £30,150 £3,500	2022

Landsdowne Drive						
Grass Verge	Part of Horticultural Contract					
Dog Bin	Replace	2021 £250s/o			2022	
Walkway - Stroma Gardens to		Total	£250			
Anglesey Avenue Opp Rockall Drive						
Grass Verge	Part of Horticultural Contract					
Trees Dog Bin	Part of on-going 3 year inspection programme Replace	2021 £250s/o			2022	
Dog Dill	перисе	Total	£250		2022	
Walkway - Stroma Gardens to						
Anglesey Avenue Grass Verge	Part of Horticultural Contract					
Grass verge	Part of on-going 3 year inspection programme - consider					
Trees	removing some trees plus bush	2020				
Grass Area London Road - Anglesey						
Avenue Junction North						
	Dort of an anima 2 year inspection programme, consider					
Trees	Part of on-going 3 year inspection programme - consider removing some trees	2020				
Grass Verge	Part of Horticultural Contract					
Hedge Grass Area London Road - Anglesey	Part of Horticultural Contract					
Avenue Junction South						
Grass Verge	Part of Horticultural Contract					
Grass Area - Anglesey Avenue						
Rockall Drive Junction						
Grass Verge	Part of Horticultural Contract					
Trees	Part of on-going 3 year inspection programme - consider removing the two Rowan trees	2020				
Walkway Rockall Drive Anglesey Avenue						
Grass Verge	Part of Horticultural Contract					
	Part of on-going 3 year inspection programme - consider	2020				
Trees	removing some of the trees	2020				
Union Corner Hall						
Grass Areas	Part of Horticultural Contract					
Hedges Dog Bin	Part of Horticultural Contract Replace	2021 £250s/o			2022	
	Part of on-going 3 year inspection programme - consider					
Trees Picket Fence	removing some of the trees Replace with same or chain-link 19 metres	2020 2020 £700s/o			2024	
FICKET FEITCE	Replace with same of chain-link 15 metres	Total	£950		2024	
Cemetery		2020			2022	
Lodge Lodge and toilets	Replace soffits and facias (budget already allocated) Replace 5 remaining wood frame windows with upvc	2020 2021 £5,589			2022 2022	
	Replace soffits, facia and guttering	,				
Toilets	Consider converting into mess room Refurbish interior	2021 Now closed t	to the public			
Tollets	Replace soffits, facia and guttering	2021 Now closed (to the public			
Office & drying room	refurbish interior & install new LED security light	2020		2024		
Chapel	consider moving mess room from here to store Redecorate interior	2022		2024		
Chaper	Install 2 LED security lights	2020		2024		
	Remove bell					
		2020		2024		
Chapel Store	Replace brick edging on exterior surround Roof to be replaced in Oct 2019	2020 2021 2019		2024 2024		
Chapel Store	Replace brick edging on exterior surround Roof to be replaced in Oct 2019 Install 2 LED security lights	2021 2019 2020		2024		
	Replace brick edging on exterior surround Roof to be replaced in Oct 2019 Install 2 LED security lights Infill windows on side elevations	2021 2019 2020 2021		2024 2024 2024	in year 3 of 10 year nlan	
Chapel Store Paths and road	Replace brick edging on exterior surround Roof to be replaced in Oct 2019 Install 2 LED security lights	2021 2019 2020		2024 2024 2024	in year 3 of 10 year plan	
Paths and road	Replace brick edging on exterior surround Roof to be replaced in Oct 2019 Install 2 LED security lights Infill windows on side elevations Install path edging on paths with no edging	2021 2019 2020 2021 2020		2024 2024 2024	in year 3 of 10 year plan	
	Replace brick edging on exterior surround Roof to be replaced in Oct 2019 Install 2 LED security lights Infill windows on side elevations Install path edging on paths with no edging	2021 2019 2020 2021 2020		2024 2024 2024	in year 3 of 10 year plan 2022	
Paths and road Common Pond Shrubs Marion Alcove	Replace brick edging on exterior surround Roof to be replaced in Oct 2019 Install 2 LED security lights Infill windows on side elevations Install path edging on paths with no edging repair path edging and resurface paths Remove overgrown shrubs around pond Repair retaining wall	2021 2019 2020 2021 2020 2022 £187-745-20 2020 £1,000 2020 £500		2024 2024 2024		
Paths and road Common Pond Shrubs Marion Alcove Seats/benches (11)	Replace brick edging on exterior surround Roof to be replaced in Oct 2019 Install 2 LED security lights Infill windows on side elevations Install path edging on paths with no edging repair path edging and resurface paths Remove overgrown shrubs around pond Repair retaining wall Refurbish wooden benches	2021 2019 2020 2021 2020 2022 £187-745-20 2020 £1,000 2020 £500 2022 £800		2024 2024 2024	2022	
Paths and road Common Pond Shrubs Marion Alcove	Replace brick edging on exterior surround Roof to be replaced in Oct 2019 Install 2 LED security lights Infill windows on side elevations Install path edging on paths with no edging repair path edging and resurface paths Remove overgrown shrubs around pond Repair retaining wall	2021 2019 2020 2021 2020 2022 £187-745-20 2020 £1,000 2020 £500		2024 2024 2024		
Paths and road Common Pond Shrubs Marion Alcove Seats/benches (11) Litter bins (4) Dog Bins (3)	Replace brick edging on exterior surround Roof to be replaced in Oct 2019 Install 2 LED security lights Infill windows on side elevations Install path edging on paths with no edging repair path edging and resurface paths Remove overgrown shrubs around pond Repair retaining wall Refurbish wooden benches Replace with concrete Replace with plastic Overlay path to ensure that it slopes towards the pond to	2021 2019 2020 2021 2020 2022 £187-745-20 2020 £1,000 2020 £500 2022 £800 2021 £1200s/o 2021 £750s/o		2024 2024 2024 2023 2023 2024	2022	
Paths and road Common Pond Shrubs Marion Alcove Seats/benches (11) Litter bins (4)	Replace brick edging on exterior surround Roof to be replaced in Oct 2019 Install 2 LED security lights Infill windows on side elevations Install path edging on paths with no edging repair path edging and resurface paths Remove overgrown shrubs around pond Repair retaining wall Refurbish wooden benches Replace with concrete Replace with plastic Overlay path to ensure that it slopes towards the pond to drain the path(142 metres)	2021 2019 2020 2021 2020 2022 £187-745-20 2020 £1,000 2020 £500 2021 £800 2021 £1200s/o		2024 2024 2024	2022	
Paths and road Common Pond Shrubs Marion Alcove Seats/benches (11) Litter bins (4) Dog Bins (3) Path around pond Fence	Replace brick edging on exterior surround Roof to be replaced in Oct 2019 Install 2 LED security lights Infill windows on side elevations Install path edging on paths with no edging repair path edging and resurface paths Remove overgrown shrubs around pond Repair retaining wall Refurbish wooden benches Replace with concrete Replace with plastic Overlay path to ensure that it slopes towards the pond to drain the path(142 metres) Replace 1.8m close board fence adjacent to the allotments (64metres)	2021 2019 2020 2021 2020 2022 £187-745-20 2020 £1,000 2020 £500 2021 £1200s/o 2021 £750s/o 2023 £20000+ 2022 £5000s/o		2024 2024 2024 2023 2024 2024	2022	
Paths and road Common Pond Shrubs Marion Alcove Seats/benches (11) Litter bins (4) Dog Bins (3) Path around pond	Replace brick edging on exterior surround Roof to be replaced in Oct 2019 Install 2 LED security lights Infill windows on side elevations Install path edging on paths with no edging repair path edging and resurface paths Remove overgrown shrubs around pond Repair retaining wall Refurbish wooden benches Replace with concrete Replace with plastic Overlay path to ensure that it slopes towards the pond to drain the path(142 metres) Replace 1.8m close board fence adjacent to the allotments	2021 2019 2020 2021 2020 2022 £187-745-20 2020 £1,000 2020 £500 2021 £1200s/o 2021 £1750s/o 2023 £20000+		2024 2024 2024 2023 2024 2024	2022	
Paths and road Common Pond Shrubs Marion Alcove Seats/benches (11) Litter bins (4) Dog Bins (3) Path around pond Fence	Replace brick edging on exterior surround Roof to be replaced in Oct 2019 Install 2 LED security lights Infill windows on side elevations Install path edging on paths with no edging repair path edging and resurface paths Remove overgrown shrubs around pond Repair retaining wall Refurbish wooden benches Replace with concrete Replace with plastic Overlay path to ensure that it slopes towards the pond to drain the path(142 metres) Replace 1.8m close board fence adjacent to the allotments (64metres)	2021 2019 2020 2021 2020 2022 £187-745-20 2020 £1,000 2020 £500 2021 £1200s/o 2021 £750s/o 2023 £20000+ 2022 £5000s/o		2024 2024 2024 2023 2024 2024	2022	
Paths and road Common Pond Shrubs Marion Alcove Seats/benches (11) Litter bins (4) Dog Bins (3) Path around pond Fence Allotments	Replace brick edging on exterior surround Roof to be replaced in Oct 2019 Install 2 LED security lights Infill windows on side elevations Install path edging on paths with no edging repair path edging and resurface paths Remove overgrown shrubs around pond Repair retaining wall Refurbish wooden benches Replace with concrete Replace with concrete Replace with plastic Overlay path to ensure that it slopes towards the pond to drain the path(142 metres) Replace 1.8m close board fence adjacent to the allotments (64metres) Replace 2 wooden 1.8m gates Remove safety surface and return to grass	2021 2019 2020 2021 2020 2022 £187-745-20 2020 £1,000 2020 £500 2021 £1200s/o 2021 £750s/o 2023 £20000+ 2022 £5000s/o		2024 2024 2024 2023 2024 2024	2022	
Paths and road Common Pond Shrubs Marion Alcove Seats/benches (11) Litter bins (4) Dog Bins (3) Path around pond Fence Allotments Butts Field Former Play Area	Replace brick edging on exterior surround Roof to be replaced in Oct 2019 Install 2 LED security lights Infill windows on side elevations Install path edging on paths with no edging repair path edging and resurface paths Remove overgrown shrubs around pond Repair retaining wall Refurbish wooden benches Replace with concrete Replace with concrete Replace with plastic Overlay path to ensure that it slopes towards the pond to drain the path[142 metres] Replace 1.8m close board fence adjacent to the allotments (64metres) Replace 2 wooden 1.8m gates Remove safety surface and return to grass Remove hedge, shrubs and trees on roadside adjacent to	2021 2019 2020 2021 2020 2022 £187-745-20 2020 £500 2021 £1200s/o 2021 £750s/o 2023 £20000+ 2022 £5000s/o 2024 £5000s/o 2021 £1400+vat		2024 2024 2024 2023 2024 2024 2024 2024	2022	
Paths and road Common Pond Shrubs Marion Alcove Seats/benches (11) Litter bins (4) Dog Bins (3) Path around pond Fence Allotments Butts Field	Replace brick edging on exterior surround Roof to be replaced in Oct 2019 Install 2 LED security lights Infill windows on side elevations Install path edging on paths with no edging repair path edging and resurface paths Remove overgrown shrubs around pond Repair retaining wall Refurbish wooden benches Replace with concrete Replace with concrete Replace with plastic Overlay path to ensure that it slopes towards the pond to drain the path(142 metres) Replace 1.8m close board fence adjacent to the allotments (64metres) Replace 2 wooden 1.8m gates Remove safety surface and return to grass	2021 2019 2020 2021 2020 2022 £187-745-20 2020 £1,000 2020 £500 2021 £1200s/o 2021 £750s/o 2023 £20000+ 2022 £5000s/o 2022 £1400+vat		2024 2024 2024 2023 2024 2024 2024 2024	2022	
Paths and road Common Pond Shrubs Marion Alcove Seats/benches (11) Litter bins (4) Dog Bins (3) Path around pond Fence Allotments Butts Field Former Play Area Hedging	Replace brick edging on exterior surround Roof to be replaced in Oct 2019 Install 2 LED security lights Infill windows on side elevations Install path edging on paths with no edging repair path edging and resurface paths Remove overgrown shrubs around pond Repair retaining wall Refurbish wooden benches Replace with concrete Replace with plastic Overlay path to ensure that it slopes towards the pond to drain the path(142 metres) Replace 1.8m close board fence adjacent to the allotments (64metres) Replace 2 wooden 1.8m gates Remove safety surface and return to grass Remove hedge, shrubs and trees on roadside adjacent to former play area	2021 2019 2020 2021 2020 2022 £187-745-20 2020 £1,000 2020 £500 2021 £1200s/o 2021 £750s/o 2023 £20000+ 2022 £5000s/o 2021 £5,000 2021 £5,000		2024 2024 2024 2023 2024 2024 2024 2024	2022	
Paths and road Common Pond Shrubs Marion Alcove Seats/benches (11) Litter bins (4) Dog Bins (3) Path around pond Fence Allotments Butts Field Former Play Area	Replace brick edging on exterior surround Roof to be replaced in Oct 2019 Install 2 LED security lights Infill windows on side elevations Install path edging on paths with no edging repair path edging and resurface paths Remove overgrown shrubs around pond Repair retaining wall Refurbish wooden benches Replace with concrete Replace with plastic Overlay path to ensure that it slopes towards the pond to drain the path(142 metres) Replace 1.8m close board fence adjacent to the allotments (64metres) Replace 2 wooden 1.8m gates Remove safety surface and return to grass Remove hedge, shrubs and trees on roadside adjacent to former play area	2021 2019 2020 2021 2020 2022 £187-745-20 2020 £1,000 2020 £500 2021 £1200s/o 2021 £750s/o 2023 £20000+ 2022 £5000s/o 2021 £5,000 2021 £5,000		2024 2024 2024 2023 2024 2024 2024 2024	2022	
Paths and road Common Pond Shrubs Marion Alcove Seats/benches (11) Litter bins (4) Dog Bins (3) Path around pond Fence Allotments Butts Field Former Play Area Hedging	Replace brick edging on exterior surround Roof to be replaced in Oct 2019 Install 2 LED security lights Infill windows on side elevations Install path edging on paths with no edging repair path edging and resurface paths Remove overgrown shrubs around pond Repair retaining wall Refurbish wooden benches Replace with concrete Replace with plastic Overlay path to ensure that it slopes towards the pond to drain the path(142 metres) Replace 1.8m close board fence adjacent to the allotments (64metres) Replace 2 wooden 1.8m gates Remove safety surface and return to grass Remove hedge, shrubs and trees on roadside adjacent to former play area Remove hedge on roadside on north side of land Boundary chestnut fence adjacent to pavilion 108 linear metres replace post & rail	2021 2019 2020 2021 2020 2022 £187-745-20 2020 £1,000 2020 £500 2021 £1200s/o 2021 £750s/o 2023 £20000+ 2022 £5000s/o 2021 £5,000 2021 £5,000		2024 2024 2024 2023 2024 2024 2024 2024	2022	
Paths and road Common Pond Shrubs Marion Alcove Seats/benches (11) Litter bins (4) Dog Bins (3) Path around pond Fence Allotments Butts Field Former Play Area Hedging Maurice Thornton	Replace brick edging on exterior surround Roof to be replaced in Oct 2019 Install 2 LED security lights Infill windows on side elevations Install path edging on paths with no edging repair path edging and resurface paths Remove overgrown shrubs around pond Repair retaining wall Refurbish wooden benches Replace with concrete Replace with concrete Replace with plastic Overlay path to ensure that it slopes towards the pond to drain the path(142 metres) Replace 1.8m close board fence adjacent to the allotments (64metres) Replace 2 wooden 1.8m gates Remove safety surface and return to grass Remove hedge, shrubs and trees on roadside adjacent to former play area Remove hedge on roadside on north side of land Boundary chestnut fence adjacent to pavilion 108 linear metres replace post & rail Boundary chestnut fence Marshfoot Lane 227 linear metres	2021 2019 2020 2021 2020 2021 2020 2022 f187-745-20 2020 f500 2020 f500 2021 f1200s/o 2021 f25000s/o 2022 f5000s/o 2022 f1400+vat 2021 f5,000 2021 f2,200 2021 f1,500 2021 f1,500		2024 2024 2024 2023 2024 2024 2024 2024	2022	
Paths and road Common Pond Shrubs Marion Alcove Seats/benches (11) Litter bins (4) Dog Bins (3) Path around pond Fence Allotments Butts Field Former Play Area Hedging Maurice Thornton Fencing	Replace brick edging on exterior surround Roof to be replaced in Oct 2019 Install 2 LED security lights Infill windows on side elevations Install path edging on paths with no edging repair path edging and resurface paths Remove overgrown shrubs around pond Repair retaining wall Refurbish wooden benches Replace with concrete Replace with plastic Overlay path to ensure that it slopes towards the pond to drain the path[142 metres) Replace 1.8m close board fence adjacent to the allotments (64metres) Replace 2 wooden 1.8m gates Remove safety surface and return to grass Remove hedge, shrubs and trees on roadside adjacent to former play area Remove hedge on roadside on north side of land Boundary chestnut fence adjacent to pavilion 108 linear metres replace post & rail Boundary chestnut fence Marshfoot Lane 227 linear metres replace post & rail Close gap in fence by outdoor gym and playpark	2021 2019 2020 2021 2020 2021 2020 2022 £187-745-20 2020 £500 2021 £1200s/o 2021 £1200s/o 2021 £750s/o 2023 £20000+ 2022 £5000s/o 2024 £3500s/o 2021 £2,200 2021 £1,500 2024 £3500s/o 2026 £6700s/o 2026 £6700s/o 2019 £100		2024 2024 2024 2024 2024 2024 2024 2024	2022	
Paths and road Common Pond Shrubs Marion Alcove Seats/benches (11) Litter bins (4) Dog Bins (3) Path around pond Fence Allotments Butts Field Former Play Area Hedging Maurice Thornton	Replace brick edging on exterior surround Roof to be replaced in Oct 2019 Install 2 LED security lights Infill windows on side elevations Install path edging on paths with no edging repair path edging and resurface paths Remove overgrown shrubs around pond Repair retaining wall Refurbish wooden benches Replace with concrete Replace with plastic Overlay path to ensure that it slopes towards the pond to drain the path(142 metres) Replace 1.8m close board fence adjacent to the allotments (64metres) Replace 2 wooden 1.8m gates Remove safety surface and return to grass Remove hedge, shrubs and trees on roadside adjacent to former play area Remove hedge on roadside on north side of land Boundary chestnut fence adjacent to pavilion 108 linear metres replace post & rail Boundary chestnut fence Marshfoot Lane 227 linear metres replace pap in fence by outdoor gym and playpark 2 gates replace with monohinge gates	2021 2019 2020 2021 2020 2021 2020 2022 £187-745-20 2020 £500 2022 £800 2021 £1200s/o 2021 £750s/o 2023 £20000+ 2022 £5000s/o 2021 £5,000 2021 £2,200 2021 £1,500 2024 £3500s/o 2026 £6700s/o 2026 £6700s/o 2026 £6700s/o 2020 £2000s/o		2024 2024 2024 2023 2024 2024 2024 2024	2022 2022 2022	
Paths and road Common Pond Shrubs Marion Alcove Seats/benches (11) Litter bins (4) Dog Bins (3) Path around pond Fence Allotments Butts Field Former Play Area Hedging Maurice Thornton Fencing	Replace brick edging on exterior surround Roof to be replaced in Oct 2019 Install 2 LED security lights Infill windows on side elevations Install path edging on paths with no edging repair path edging and resurface paths Remove overgrown shrubs around pond Repair retaining wall Refurbish wooden benches Replace with concrete Replace with plastic Overlay path to ensure that it slopes towards the pond to drain the path[142 metres) Replace 1.8m close board fence adjacent to the allotments (64metres) Replace 2 wooden 1.8m gates Remove safety surface and return to grass Remove hedge, shrubs and trees on roadside adjacent to former play area Remove hedge on roadside on north side of land Boundary chestnut fence adjacent to pavilion 108 linear metres replace post & rail Boundary chestnut fence Marshfoot Lane 227 linear metres replace post & rail Close gap in fence by outdoor gym and playpark	2021 2019 2020 2021 2020 2021 2020 2022 £187-745-20 2020 £500 2021 £1200s/o 2021 £1200s/o 2021 £750s/o 2023 £20000+ 2022 £5000s/o 2024 £3500s/o 2021 £2,200 2021 £1,500 2024 £3500s/o 2026 £6700s/o 2026 £6700s/o 2019 £100		2024 2024 2024 2024 2024 2024 2024 2024	2022	
Paths and road Common Pond Shrubs Marion Alcove Seats/benches (11) Litter bins (4) Dog Bins (3) Path around pond Fence Allotments Butts Field Former Play Area Hedging Maurice Thornton Fencing	Replace brick edging on exterior surround Roof to be replaced in Oct 2019 Install 2 LED security lights Infill windows on side elevations Install path edging on paths with no edging repair path edging and resurface paths Remove overgrown shrubs around pond Repair retaining wall Refurbish wooden benches Replace with concrete Replace with concrete Replace with plastic Overlay path to ensure that it slopes towards the pond to drain the path(142 metres) Replace 1.8m close board fence adjacent to the allotments (64metres) Replace 2 wooden 1.8m gates Remove safety surface and return to grass Remove hedge, shrubs and trees on roadside adjacent to former play area Remove hedge on roadside on north side of land Boundary chestnut fence adjacent to pavilion 108 linear metres replace post & rail Boundary chestnut fence Marshfoot Lane 227 linear metres replace post & rail Close gap in fence by outdoor gym and playpark 2 gates replace with monohinge gates Swings basket X1 and flats X2 replace seats	2021 2019 2020 2021 2020 2021 2020 2022 f187-745-20 2020 f500 2020 f500 2021 f1200s/o 2021 f25000s/o 2022 f1400+vat 2021 f5,000 2021 f2,000 2021 f1,500 2024 f3500s/o 2026 f6700s/o 2026 f6700s/o 2021 f1,500		2024 2024 2024 2024 2024 2024 2024 2024	2022 2022 2023	

	Toddler swings replace seats	2021	£250			2023
	Toddler swings replace frame	2024	£1400s/o			
	Disabled roundabout (requires adjustment now) replace unit	2024	£5000s/o			2023
	Slide Unit	2024	£25000s/o			
	City Spinner	2024	£1200s/o			
	2 Springers	2024	£1200s/o			
	Toddler Climbing Unit		£10000s/o			
	Log surround to seats remove and infill	2019	£100			2020
	2 Litter Bins replace		£1600s/o			2022
	Picnic Bench replace. Metal		£1100s/o			2023
	Memorial Bench replace		£1200s/o			2023
Chatanani	Fence around playpark replace		£15000s/o		2024	
Skatepark	2 Information Signs replace		£1200s/o		2024	
	Bin replace. Normal and recycling		£600s/o			2022
Pavilion	Exterior - tarmac path from emergency exit	2020	£780			2020
	Exterior - replace bricks on edge of path by emergency exit	2020				2020
Outdoor Gym Hags	Powerpush replace	2025	£3600s/o			
	Ski Stepper Replace	2025	£3200s/o			
	Health Walker Replace	2025	£2800s/o			
	Handle Boat Replace	2025	£2500s/o			
	Push Hands Replace	2025	£2300s/o			
Seats	3 benches replace		£1900s/o			
	3 litter bins replace with non-metal. Double bin with					
Bins	recycling option	2020	£2,000			2022
Dog bins	2 dog bins replace with non-metal	2020	£500			2022
Dog bills	2 dog biris replace with non-metal	2020	1300			2022
Battle Road Allotments and Play Area						
<u> </u>						
Play Area	2 monohinge gates replace	2025	£2,000			
,	2 benches replace	2024	£1,450			
	1 litter bin replace non-metal. Double bin with recycling		,			
	option	2024	£600			
	Slide (Wicksteed) replace		£3800s/o			
			£7500s/o			2023
	Toddler Slide (Hargs) replace	2029	£/500\$/0			2023
	C-f-bffff	2020	64.500			2022
	Safety surface under slide replace with rubber safety surface	2020	£4,500			2023
	Springer replace		£700s/o			2023
	Wirlybird roundabout (Wicksteed) replace		£2800s/o			2023
	Swings 2 sets plus safety surface replace		£3500s/o			2023
	Paths reset edging on some of the paths	2021	£2,000		2024	
Allotments	Replace three wooden boundary gates with metal gates	2021	£3,000		2024	
Ersham Road Triangle						
	Replace 28 linear metres of chain-link fence 3 metres in					
	height	2025	£2,000	N/A		
Fence	neight			N/A		
Fence	Replace 16 liners metres of split chestnut 3 rail fence	2022	£600	11/71		
Fence Benches	9	2022 2025	£600 £1,200	N/A		
	Replace 16 liners metres of split chestnut 3 rail fence					
Benches Bins	Replace 16 liners metres of split chestnut 3 rail fence Replace 2 benches Replace litter bin with non metallic	2025	£1,200	N/A		
Benches Bins Dog bins	Replace 16 liners metres of split chestnut 3 rail fence Replace 2 benches Replace litter bin with non metallic Replace dog bin with non metallic	2025 2025 2021	£1,200 £300 £250	N/A N/A N/A		
Benches Bins	Replace 16 liners metres of split chestnut 3 rail fence Replace 2 benches Replace litter bin with non metallic Replace dog bin with non metallic Replace 5 bar field gate	2025 2025 2021 2025	£1,200 £300 £250 £500	N/A N/A N/A N/A		
Benches Bins Dog bins	Replace 16 liners metres of split chestnut 3 rail fence Replace 2 benches Replace litter bin with non metallic Replace dog bin with non metallic	2025 2025 2021	£1,200 £300 £250	N/A N/A N/A		